

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE PTE LTD		Ref:	CS3/ASM22011007/Gvy3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	11/11/2022	
	ATTN: HO WINNIE		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 7036K	Veh. Inspected	FBL 7850E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S2M04DY8	Excess (\$)	0.00	
	Assign From	HO WINNIE	Assign Date	03/11/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA GLR1251WH	c.c	125	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	LWBJC74A8H1000041	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	80/90-18	GOLDEN BOY	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	3.60-18	GOLDEN BOY	5 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, O/S AND N/S BODY.				
5.	5. General Information				
	Accident Date	01/11/2022	Inspect Date / Time	04/11/2022 (04:20 PM)	
	Survey held at	MCS AUTO			
	NO. 1100 SERANGOON ROAD SINGAPORE 328195				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			
	Poport Pof No. CS2/ASM22011007/Cvv/2o2				

Report Ref No. CS3/ASM22011007/Gvy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor