

HIAP LEK AUTOMOBILE TRADING

160 Sin Ming Drive
Sin Ming Autocity
#05-17
Singapore 575722

Tel : 6453 1743 Fax: 6266 8605
E-Mail : hiaplek@hotmail.com

Date: 26th JULY 2022

Vehicle No : GY 1275C
Make/ Model : TOYOTA DYNA
Year of Manufacture : 06 JANUARY 2021
Chassis No. : JTFUF34Y103010026
Colour : WHITE
Name : RH SYNERGY (S) PTE LTD
Address : 26 KAKI BUKIT PLACE
SINGAPORE 416204

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Third Party Accident Claim for Motor Vehicle No. GY 1275C
Date of Accident: 18th MAY 2022

..... **S\$11,300.00**
(Lump Sum)

Singapore Dollars: ELEVEN Thousand THREE Hundred Only

PAR Automotive Consultancy

Regn. No: S2986974L

Mailing Address : Blk 310 Shunfu Road #07-213, Singapore 570310. Tel : 645 31173, Fax : 645 36131.

Report No: 0066-22-HL

26 July 2022

RH Synergy (S) Pte Ltd
c/o Hiap Lek Automobile Trading
160 Sin Ming Drive #05-17
Sin Ming Autocity
Singapore 575722

INVOICE No. **0066-22-HL**

Vehicle No. **GY1275C**

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$918.00
	Total amount payable	<u>\$918.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Mailing Address : Blk 310 Shunfu Road #07-213, Singapore 570310. Tel : 645 31173, Fax : 645 36131.

Report No: 0066-22-HL

26 July 2022

ACCIDENT VEHICLE SURVEY REPORT

RH Synergy (S) Pte Ltd
c/o Hiap Lek Automobile Trading
160 Sin Ming Drive #05-17
Sin Ming Autocity
Singapore 575722

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	GY1275C	<i>Odometer:</i>	91815km
<i>Make & Model:</i>	Toyota Dyna	<i>Colour:</i>	White
<i>Chassis number:</i>	JTFUF34Y103010026	<i>Date of accident:</i>	18/05/2022
<i>Year of Regn.:</i>	06/01/2005	<i>Date inspected:</i>	18/05/2022
<i>Repairer at:</i>	Hiap Lek Automobile Trading 160 Sin Ming Drive #05-17 Sin Ming Autocity Singapore 575722	<i>Date inspected (After Repair):</i>	30/05/2022

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	5mm/Dunlop	5mm/Dunlop	185R14
<i>Rear:x2</i>	4mm/Doublestar	4mm/Doublestar	155R12

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

Report No: 0066-22-HL

Vehicle No: GY1275C

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Tailgate	1	bent	2,017.40	2,017.40
Tailgate hinges	4	bent	412.40	412.40
Rear sidegate lock RH/LH	2	repair	242.60	0.00
Rear end panel	1	bent	456.82	456.82
Rear tail lamp bracket RH/LH	2	bent	142.00	142.00
Rear tail lamp RH/LH	2	fractured	502.80	502.80
Rear tailgate stopper bracket RH/LH	2	bent	160.00	160.00
Rear tailgate stopper rubber RH/LH	2	deformed/abraded	144.80	144.80
Rear number plate lamp RH/LH	2	fractured	172.00	172.00
Rear number plate bracket	1	bent	273.70	273.70
Front wiper panel	1	fractured	243.40	243.40
Front wiper panel corner RH/LH	2	fractured	375.40	375.40
Front air duct	1	deformed	45.60	45.60
Front corner panel RH	1	dented	466.00	466.00
Front windscreen rubber	1	necessary	256.90	256.90
Front centre panel	1	buckled	876.30	876.30
Front centre panel protector center	1	fractured	291.53	291.53
Front centre panel protector RH/LH	1	fractured	399.50	399.50
Front grille emblem "Toyota" logo	1	necessary	53.80	53.80
Front grille	1	fractured	426.25	426.25
Front headlamp LH/RH	2	fractured	1,146.60	1,146.60
Front headlamp protector LH?RH	2	deformed	44.00	44.00
Front bumper	1	bent	885.50	885.50
Front bumper bracket RH/LH	2	bent	323.44	323.44
Air con blower motor	1	fractured/shorted	1,431.90	1,431.90
		<i>Subtotal before discount</i>	11,790.64	11,548.04
		<i>Percentage discount 0% and 25%</i>	0.00	2,887.01
		Sub-total 1	11,790.64	8,661.03

PAR Automotive Consultancy

Annex A: Page 2
Report No: 0066-22-HL-GY1275C

Tailgate checker plate	1 bent	500.00	500.00
Sticker "70km/h"	1 necessary	10.00	10.00
Sticker "4 pax"	1 necessary	10.00	10.00
Rear number plate	1 bent	25.00	25.00
Front number plate	1 bent	25.00	25.00
	<i>Subtotal before discount</i>	570.00	570.00
	<i>Percentage discount 0% and 0%</i>	0.00	0.00
	Sub-total 2	570.00	570.00
	Parts-total	12,360.64	9,231.03

LABOUR

1. To straighten and panel beating front inner panel, rear deck frame member, rear and front frame members. To cut/weld rear end panel and front panel. To remove and refit above parts.		2,500.00	2,000.00
2. To putty, re-spray painting and polish affected areas.		2,200.00	1,840.00
3. To check and rectify wiring system.		100.00	80.00
4. To rust proof affected areas.		180.00	150.00
5. To remove and refit front windscreen glass.		150.00	100.00
7. To remove, refit air con system and recharge air con gas.		150.00	120.00
8. To remove and refit dashboard assy to assist repair.		350.00	280.00
9. To reinstate company advertisement sticker on affected areas.		400.00	400.00
	Labour total	6,030.00	4,970.00
	Parts & Labour total	18,390.64	14,201.03

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is : **\$11,300.00**
and the recommended number of working days for the repairs is : **14**


B J Loi (I Eng. MIMI, AIRTE)
Automotive Appraiser