

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile								
	MINISTRY OF DEF	FENCE		Ref:	CC2/MIDA22011019/GNpq2				
	HQ TRANSPORT (COMMAND		Date:	28/02/2023				
	KRANJI CAMP 3 151 CHOA CHU KA	ANG WAYSINGAPORE 688248							
				Code:	MIDA				
1.	Policy Particulars :- THIRD PARTY CLAIM								
	Insured Veh.	MID 46274	Veh. Inspected		SHC 7172E				
	Policy No.	OA22031393	Coverage (\$)		0.00				
	Claim No.	CY22/MID46274/311022/0038	Excess (\$)		0.00				
	Assign From		Assign Date		04/11/2022				
2.		Vehicle Partic	culars & Condition	on					
	Make & Model	HYUNDAI 140	c.c		1685				
	Engine No.	HIDDEN	Year of Reg.		2016				
	Chassis No.	KMHLB41UMGU086979	Colour		YELLOW				
	Odometer	-	Steering		IN ORDER				
	Brakes	IN ORDER	Modification		NIL				
	General	GOOD							
3.		Conditi	ons of Tyres						
		Size	Make		Balance				
	R/H Front Tyre	195/65 R15	WEST LAKE		6 mm				
	L/H Front Tyre	195/65 R15	WEST LAKE		6 mm				
	R/H Rear Tyre	195/65 R15	WEST LAKE		6 mm				
	L/H Rear Tyre	195/65 R15	WEST LAKE		6 mm				
4.		Description of Damages							
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.								
	DAMAGES SEE DI	DAMAGES SEE DETAILS.							
5.		Genera	Information						
	Accident Date	31/10/2022	Inspection Date	е	04/11/2022				
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD						
		59 LOYANG DRIVE SINGAPORE 508969							
5a.		Re	emarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.								
5b.		Estimate Days of Repair							
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7172E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	BROKEN	553.00	553.00
1	REAR BUMPER LOWER COVER	SERVICEABLE	228.00	-
1	REAR REINFORCEMENT	SERVICEABLE	428.40	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET LH/RH @\$35.60	SERVICEABLE	71.20	-
2	REAR BUMPER REFLECTOR LH/RH @\$32.00	SERVICEABLE	64.00	-
	LESS 20% DISCOUNT		-273.32	-115.00
			1,093.28	460.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
			185.70	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		450.00	280.00
	SPRAY PAINTING CHARGE .		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR .		60.00	40.00
	CHECK LIGHTING & WIRING.	NOT NECESSARY	40.00	
			850.00	570.00
	GRAND TOTAL		2,128.98	1,080.00

RECOMMENDED COST OF LUMP SUM REPAIRS		850.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC2/MIDA22011019/GNpq2



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7172E

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7172E

RE-INSPECTION





