



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5576K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	O/S CORNER DEFLECTOR (DISC 10%)	CRACKED	328.33	295.50
1	O/S CORNER BUMPER (DISC 10%)	CRACKED	888.98	800.08
1	FRT O/S LIGHT BEZEL (DISC 10%)	MISSING	298.28	268.45
1	HEADLAMP,BEAM:DIPPED,FOR VOLVO B9TL BUS (DISC 10%)	MISSING	445.00	400.50
1	HEADLAMP,MAIN BEAM:FOR VOLVO B9TL BUS	NOT NECESSARY	372.30	-
1	INDICATOR LIGHT:AMBER,FRT,VOLVO B9TL BUS	NOT NECESSARY	597.30	-
1	DOME,FRONT:LOWER,CLASS 2,FOR VOLVO B9TL	TO REPAIR SEE LABOUR	3,391.95	-
			6,322.14	1,764.53
<b>LABOUR</b>				
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF DOME,FRONT:LOWER,CLASS 2,FOR VOLVO B9TL.		1,590.00	1,060.00
	SPRAY PAINT.		956.00	786.00
			2,546.00	1,846.00
<b>GRAND TOTAL</b>			<b>8,868.14</b>	<b>3,610.53</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>2,900.00</b>

Report Ref No. NS/INC22011020/Rqcm4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.