

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22011043/UNP3Q2
Date: 15/11/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00263852100
Claimant Vehicle No :	GBC6702D	Insured Vehicle No :	SMA9323A
Date of Loss:	03/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D207914/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC6702D	Engine No:	KU2632
Make & Model:	ISUZU TFS86JDR, 2.5 D (A)	Chassis No:	MPATFS85JDT003808
Reg. Date:	19/06/2013 (Man. Year: 2013)	Odometer:	137151 km
Colour:	Blue		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/70 R16	Rear Tyre Size:	245/70 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,091.49	2,671.60	2,419.89	47.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	890.00	1,610.00	64.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,591.49	3,561.60	4,029.89	53.08
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	7,591.49	2,800.00	4,791.49	63.12

INSPECTION

Date of Assignment:	04/11/2022		
Date Inspected:	10/11/2022	Inspected At:	Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406 Singapore 539195
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 15 Nov 2022)	
Parts:	N/A	ISUZU TFS86JDR 2.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC6702D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,300.74 FL	*1,450.00 FL
2	1		*REAR TAILGATE LOCK	Not Necessary	185.90 FL	*- FL
3	1		*REAR TAILLAMP -L/H	Not Necessary	500.77 FL	*- FL
4	1		*REAR END PANEL	Repair	585.00 FL	*- FL
5	1		*REAR BUMPER	Dented / Warped	1,097.90 FL	*905.00 FL
6	2		*REAR BUMPER BRACKETS	Repair	210.00 FL	*- FL
7	1		*REAR BUMPER TOP STEP GARNISH	Warped	470.15 FL	*405.00 FL
8	2		*REAR NUMBER PLATE LAMPS	Cracked	136.00 FL	*136.00 FL
9	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
10	1		*REAR TAILGATE 70KM/H STICKER	Necessary	28.00 FS	*10.00 FS
11	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,914.46	3,106.00
- List Item Discount on L Items 15.00/15.00% (\$)	822.97	434.40
Total Parts (\$)	5,091.49	2,671.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	40.00
3	TO APPLY UNDERCOATING	New	100.00	30.00
4	PANEL BEATING	New	1,200.00	400.00
5	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,000.00	400.00
			Gross Labour Cost (\$\$)	2,500.00
				890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >