

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22011051/DWY3M4**Date:** 03/03/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001912075
Claimant Vehicle No :	SMT8464H	Insured Vehicle No :	SKR3761S
Date of Loss:	02/11/2022	Nature of Claim:	TP
		Claim No:	289324

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT8464H	Engine No:	2ZR2C27511
Make & Model:	TOYOTA COROLLA, 1.8 Sport Ascent CVT (A)	Chassis No:	JTNK93BE403003650
Reg. Date:	21/07/2020 (Man. Year: 2018)	Odometer:	29279 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,438.72	1,572.05	10,866.67	87.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	700.00	4,620.00	86.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,758.72	2,272.05	15,486.67	87.21
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	17,758.72	1,800.00	15,958.72	89.86
+ GST 8.00/8.00% (S\$)	1,420.70	144.00	1,276.70	89.86
Nett Amount (S\$)	19,179.42	1,944.00	17,235.42	89.86

INSPECTION

Date of Assignment:	04/11/2022	
Date Inspected:	07/11/2022	Inspected At:
Estimated Period of Repair:	3.0 days	

C. S. ONG AUTO PTE LTD
BLOCK 10 ANG MO KIO IND PK 2A
#02-16 AMK AUTOPOINT, SINGAPORE 568047

Adjuster: BRYAN TANI**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2023)
Parts:	143	TOYOTA COROLLA 1.8 Sport Ascent CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT8464H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	2,439.00 FL	*865.20 FL
2	2		*REAR BUMPER SIDE RETAINER LH / RH	Not Necessary	388.00 FL	*- FL
3	1		*REAR BUMPER SCRUFF PLATE	Not Necessary	587.00 FL	*- FL
4	1		*REAR BUMPER LOWER BLACK	Distorted	735.00 FL	*532.60 FL
5	2		*REAR BUMPER REFLECTOR LH / RH	Not fitted	264.00 FL	*- FL
6	1		*REAR BUMPER LOWER LID	Not fitted	538.00 FL	*- FL
7	1		*REAR BUMPER SPONGE	Not Necessary	543.00 FL	*- FL
8	1		*REAR BUMPER CARRIER	Not fitted	332.00 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT BAR	Dented	946.00 FL	*671.60 FL
10	2		*REAR BUMPER PARKING SENSOR	Not fitted	626.00 FL	*- FL
11	2		*REAR BUMPER PARKING SENSOR HOLDER	Not Necessary	116.00 FL	*- FL
12	1		*REAR BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	1,157.00 FL	*- FL
13	2		*TAILLAMP ASSY LH / RH	Not Necessary	2,563.80 FL	*- FL
14	2		*TAIL LAMP LOWER BRACKET LH / RH	Not Necessary	588.00 FL	*- FL
15	1		*REAR END PANEL	Not Necessary	1,209.00 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	589.00 FL	*- FL
17	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
18	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
19	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,800.80	2,089.40
- List Item Discount on L Items 10.00/25.00% (\$\$)	1,362.08	517.35
Total Parts (\$\$)	12,438.72	1,572.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	400.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	300.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR REAR PARKING SENSOR	New	100.00	0.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
8	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	0.00
Gross Labour Cost (\$\$)			5,320.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >