



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22011054/Rny3m4 Date: 16/05/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 6176G	Veh. Inspected	XE 5471E
Policy No.	D22099240	Coverage (\$)	0.00
Claim No.	D22003444MFCV	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	04/11/2022
2. Vehicle Particulars & Condition			
Make & Model	VOLVO FMX380 64R RSS DC	c.c	10837
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	YV2X9R0DXLA854798	Colour	RED
Odometer	221871 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	295/80R22.5	TRIANGLE	8 mm
L/H Front Tyre	295/80R22.5	TRIANGLE	8 mm
R/H Rear Tyre	295/80R22.5 (D/D)	TRIANGLE	8/8 mm
L/H Rear Tyre	295/80R22.5 (D/D)	TRIANGLE	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS			
5. General Information			
Accident Date	01/11/2022	Inspection Date	08/11/2022
Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD SINGAPORE 758133		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	