



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 3818U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR S9 (SN)	DEFORMED	2,753.90	2,753.90
1	PROTECTING PLATE REA (SN)	CUT	439.80	439.80
10	BLIND RIVET 4.0*21 P (SN)	NECESSARY	50.00	50.00
10	BUMPER CLIP 8x8,5 (SN)	NECESSARY	82.00	82.00
1	BUMPER RAIL REAR S90 (SN)	* CHECK	1,621.60	-
1	V031383527/BUMPER BR (SN)	* CHECK	182.10	-
1	PARK SENSOR 29db 90 (SN)	* CHECK	215.50	-
			5,344.90	3,325.70
LABOUR				
	TO REPLCE REAR BUMPER, REAR LOWER SPOILER, ETC.		350.00	350.00
	TO PUTTY SPRAY PAINT ON REAR BUMPER, ETC.		750.00	750.00
	RENTAL CAR FOR 3 DAYS.	* CHECK	600.00	-
			1,700.00	1,100.00
GRAND TOTAL			7,044.90	4,425.70
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2619.20 NETT)				4,425.70

Report Ref No. CS/TP22011057/Gvy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.