

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122011060/EVY3Q2**Date:** 28/12/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJP339X**Insured Vehicle No :** SKT6675C

Date of Loss: 31/10/2022

Nature of Claim: TP

Claim No: CDMPG22002357

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJP339X**

Make & Model: ADIVA AD1 200, 190cc 3W

Engine No: 201021C0292PT153

Reg. Date: 20/05/2021 (Man. Year: 2021)

Chassis No: SADFB2AS7M1021187

Colour: Black

Odometer: 15969 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19

Rear Tyre Size: 235/55 R19

Front Left Side: Goodyear 4 mm

Rear Left Side: Goodyear 4 mm

Front Right Side: Goodyear 4 mm

Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,954.40	7,346.30	13,608.10	64.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,158.00	4,901.00	3,257.00	39.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,112.40	12,247.30	16,865.10	57.93
+ GST 7.00/7.00% (S\$)	2,037.87	857.31	1,180.56	57.93
Nett Amount (S\$)	31,150.27	13,104.61	18,045.66	57.93

INSPECTION

Date of Assignment: 04/11/2022

Date Inspected: 08/11/2022

Inspected At:

Wearnes automotive Pte Ltd (HQ)
45 LENG KEE ROAD
Singapore 159103

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Please be informed that vehicle convert to OD claim.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$9,155.40 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Dec 2022)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP339X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BMPER -FRONT	Dented	2,179.00 FS	*2,179.00 FS
2	1		*LH BRACKET -BUMPER	Necessary	31.20 FS	*31.20 FS
3	15		*BUMPER NUT XF	Necessary	84.00 FS	*84.00 FS
4	1		*CTR BRACKET -BMPR MNT	*Check	328.60 FS	*- FS
5	1		*LH COVER -AIR DUCT MOD	Cut	98.60 FS	*98.60 FS
6	1		*LH DUCT -BRK CLPR CLT	Necessary	30.60 FS	*30.60 FS
7	1		*PLATE -BLANKING LH	Crushed	55.90 FS	*55.90 FS
8	1		*BLADE -BUMPER LH	Cut	233.30 FS	*233.30 FS
9	1		*PLATE -BLANKING LH	Cut	99.30 FS	*99.30 FS
10	1		*COVER -TWNG HK OPNNG	Cut	820.50 FS	*820.50 FS
11	1		*COVER FOG LAMP LH	*Check	192.70 FS	*- FS
12	1		*PANEL -NOSE	*Check	129.20 FS	*- FS
13	1		*GRILLE -RADIATOR	*Check	494.00 FS	*- FS
14	1		*SURROUND -RAD GRILLE	*Check	1,147.40 FS	*- FS
15	1		*DEFLECTOR LH	*Check	98.00 FS	*- FS
16	1		*HEADLAMP LH	*Check	4,615.80 FS	*- FS
17	3		*RING -RETAINING	*Check	11.70 FS	*- FS
18	1		*WHEEL -ROAD -ALLOY	Cut	1,661.70 FS	*1,661.70 FS
19	1		*PANEL -FENDER LH	Repair	1,186.40 FS	*- FS
20	1		*BAR -SUPPORT LOWER	*Check	417.90 FS	*- FS
21	1		*PANEL -REINFORCEMENT	*Check	1,222.20 FS	*- FS
22	1		*FRAME -SUPPORT LH	*Check	148.00 FS	*- FS
23	1		*BUMPER BRACKET RH	Not Necessary	98.60 FS	*- FS
24	1		*FOGLAMP COVER RH	Not Necessary	192.70 FS	*- FS
25	1		*MESH-GRILLE RH	Not Necessary	270.70 FS	*- FS
26	1		*MESH-GRILLE LH	Cut	270.70 FS	*270.70 FS
27	1		*BLADE -BUMPER RH	Not Necessary	233.30 FS	*- FS
28	1		*BLADE -BUMPER LOWER R	Not Necessary	233.30 FS	*- FS
29	1		*BLADE -BUMPER LOWER L	Cut	233.30 FS	*233.30 FS
30	1		*BRACKET -BUMPER RH	Not Necessary	31.20 FS	*- FS
31	1		*BEAM -BUMPER	Not Necessary	413.00 FS	*- FS
32	1		*MOUNTING -BRACKET LH	*Check	142.90 FS	*- FS
33	1		*LINER -WHEELARCH LH	Broken	274.50 FS	*274.50 FS
34	1		*WHEEL MOULDING FRT L	Missing	331.80 FS	*331.80 FS
35	1		*FINISHER -VENT LH	Necessary	279.30 FS	*279.30 FS
36	2		*SENSOR	Broken	662.60 FS	*662.60 FS
37	2		*SENSOR -PRKNG AID SYS	Not Necessary	760.40 FS	*- FS
38	1		*BADGE -RAD GRILLE	Not Necessary	1,240.10 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	20,954.40	7,346.30
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT BUMPER ,FRT MESH GRILLE LH ,FOG LAMP LH, INSERT LH ,FRT FENDER LH ,FRT ARC MLDG LH ,FRT LINER LH ,HEADLAMP LH,ETC	New	3,500.00	1,950.00
2	TO SPRAY FRT BUMPER ,FRT FENDER LH ,BONNET ,ETC	New	3,500.00	2,000.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
4	TO FOCUS HEADLAMP (*Check)	New	207.00	0.00
5	TO REPLACE FRT RIM LH	New	50.00	50.00
6	WHEEL ALIGNMENT	New	280.00	280.00
Gross Labour Cost (\$\$)			8,158.00	4,901.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >