



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 9982S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR EXHAUST PIPE	NOT NECESSARY	858.00	-
1	REAR LH LOWER ARM	BENT	308.00	308.00
1	REAR LH TOP ARM	NOT NECESSARY	264.00	-
2	REAR LH CONTROL ARM @\$275.00	DAMAGED (1PC ONLY)	550.00	275.00
1	REAR BUMPER LOWER LIP	NOT NECESSARY	374.00	-
1	REAR LH WHEEL BEARING	NOT NECESSARY	462.00	-
	LESS 10% DISCOUNT		-281.60	-58.30
			2,534.40	524.70
2	REAR EXHAUST CHROME @\$528.00 (SN)	CUT	1,056.00	300.00
	LESS 10% DISCOUNT		-105.60	-
			950.40	300.00
	<b><u>LABOUR</u></b>			
	TO CHECK WHEEL ALIGNMENT.		100.00	80.00
	REMOVE & REINSTALL REAR LH SUSPENSION.		400.00	150.00
			500.00	230.00
<b>GRAND TOTAL</b>			<b>3,984.80</b>	<b>1,054.70</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>800.00</b>

Report Ref No. CS/SPF22011062/Any3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000**

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.