7/20/23, 8:53 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB22011064/RYA3Q2

20/07/2023 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle SHF178U Insured Vehicle No: SLL9144D

No:

Date of Loss: 30/10/2022 Nature of Claim: TP Claim No: MFL2022D0006760

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF178U**

TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) 2ZR2G88778 Make & Model: Engine No:

Reg. Date: 01/12/2020 (Man. Year: 2020) Chassis No: JTDKB3FU303091830

Colour: Odometer: 124022 km Maroon

Engine Capacity: 1798 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,292.70	60.00	3,232.70	98.18
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,992.00	650.00	1,342.00	67.37
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	5,284.70	710.00	4,574.70	86.56
	+ Loss of Use (7.0)	x S\$40.00/day) (S\$)	280.00		
	+ Car Rental (7.0)	x S\$73.00/day) (S\$)	511.00		

INSPECTION

Date of Assignment: 04/11/2022

Strides Automotive Services Pte Ltd (Woodlands) Date Inspected:

Nett Liability (S\$)

60 Woodlands Industrial Park E4 07/11/2022 Inspected At:

Singapore 757705

1,501.00

Estimated Period of Repair: 1.0 days

MOHD RASUL Adjuster: Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Reference

7/20/23, 8:53 AM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jan 2023)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHF178U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*STICKER STRIDES TAXI (DOOR) (SN)	Necessary	60.00 F	*60.00 F
2	1	*PANEL SUB-ASSY ,FRONT DOOR LH	Repair	1,407.80 F	*- F
3	1	*PANEL SUB-ASSY ,REAR DOOR ,LH	Repair	1,401.70 F	*- F
4	1	*DOOR OUTER HANDLE FRONT LH	Repair	423.20 F	*- F
F=Fra	anchise part.		Total Parts (S\$)	3,292.70	60.00
		D 1 11111			

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	936.00	450.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
		Gross Labour Cost (S\$)	1,992.00	650.00
	Renort was unsub	mitted during this print-out.		

< END OF ESTIMATES >