

Case Details

Case Reference Number : TAX/10/22/2096
Type of Repair : Accident Repair
Vehicle Registration Number : SHF178U

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-19706-ID
Assigned By : Tan Lee Ge #

Insurance Company Name : India International Insurance Pte Ltd
Accident Date and Time : 30/10/2022 03:45 AM
Vehicle Age(In Months) :-

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,407.80	1,407.80	25.00	1,055.85	Replace	1	0	Repair	R
Standard	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	mu
Standard	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,401.70	1,401.70	25.00	1,051.28	Replace	1	0	Repair	R
One Time Key In	Main			DOOR OUTER HANDLE FRONT , LH	1	423.20	423.20	25.00	317.40	Replace	1	0	Repair	R
Total Spare Part Cost									2,484.53	Surveyor Total		60.00		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									2,777.48	Final Sur Total		60.00		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	676.00	200	

Total:

676.00

200.00

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR LH	378.00	200	

Total:

378.00

450.00

11/7/22, 3:11 PM

https://vacsweb.smrt.com.sg/Estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESRAY REAR DOOR LH	378.00	200	
3	Main	TO RESPRAY DOOR HANDLE	180.00	50	
Total:			936.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 X _{an}	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 X _{an}	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 X _{an}	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0 X _{an}	
Total:			380.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,777.48	60.00
Total Labour Cost	676.00	200.00
Total Spray Painting	936.00	450.00
Other	380.00	0.00
Overall Total	4,769.48	710.00
Lump Sum Repair Option	<input type="checkbox"/>	<input type="checkbox"/>
Lump Sum Total	0.00	710.00
Surveyor Approved Amount		710.00
No of Repair Days*	4	2
Remarks	-	PART BY PART / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP: 9701 0028 rasul@lkkauto.com
Surveyor Name		Rasul
Signature		

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 07/11/2022

Survey Date

Save

Clear