

Vehicle Diagnostic Report

The Report is created by **LAUNCH** X-431

Repair Shop

Shop Name: AUTOSPRINT PTE LTD

Address:24 LENG KEE ROAD #07-01/02 Leng Lee AutoPoint, Singapore 159096

SINGAPORE SINGAPORE

Zip Code:159096

Telephone:69118331 fax62517438

Email:enquiry@autospring.com.sg

SN:989890010977

Test Time:2022-10-03 13:55:17

Technician Name:Alan



Vehicle Information

Make:Mercedes-Benz

Model:205.077 - C 200 Sedan/C 260 Sedan

VIN:W1K2050772R581704

Odometer:38306 km

Vehicle Software Version: V49.85

Diagnostic Application Version: V7.03.030

Diagnostic path:Automatically Search >48V - Starter-alternator(RSG48V1_ODX)





DTC

DTC	Description	State
P061B00	The torque calculation of the control unit has a malfunction	STORED
P062068	The output for the actuation of the alternator has a malfunction. There is incomplete information.	STORED
P0A1A92	This error code can be ignored and erased.	STORED
P0A5929	The current sensor of electric machine A has a malfunction. There is an invalid signal.	STORED
P0AFA16	The power supply of the high-voltage on-board electrical system is too low. The limit value for electrical voltage has not been attained.	STORED
POAFA68	The power supply of the high-voltage on-board electrical system is too low.There is incomplete information.	STORED
P0AFB17	The power supply of the high-voltage on-board electrical system is too high. The limit value for electrical voltage has been exceeded.	STORED

P0E0018	The current sensor for phase U of electric machine A has a malfunction. The limit value for current has not been attained.	STORED
B21E368	The starter battery has opened the battery disconnect switch.There is incomplete information.	STORED