

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011070/ENP3Q2**Date:** 12/06/2023**REFERENCE**

Insured/Claimant:	HIAP SENG TRANSPORT PTE LTD	Policy No:	DMCVSNW00058462201		
Date of Loss:	31/10/2022	Nature of Claim:	OD	Claim No:	SNM22D207812/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE3031E		Engine No:	50547181714720
Make & Model:	MAN TGS 26.400, 10.5 D 6X4 BBS (M)		Chassis No:	WMA26SZZ9HM742151
Reg. Date:	06/06/2017 (Man. Year: 2017)		Odometer:	48818 km
Colour:	White			
Engine Capacity:	10518 cc			
Market Value/New Car Price:	S\$120,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5
Front Left Side:	Firemax 4 mm	Rear Left Side:	Firemax 4 mm
Front Right Side:	Firemax 4 mm	Rear Right Side:	Firemax 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,434.28	23,092.93	13,341.35	36.62
Miscellaneous Items	480.00	480.00	0.00	0.00
Labour	6,900.00	4,250.00	2,650.00	38.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,814.28	27,822.93	15,991.35	36.50
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	43,814.28	25,822.93	17,991.35	41.06
+ GST 7.00/8.00% (S\$)	3,067.00	2,065.83	1,001.17	32.64
Nett Amount (S\$)	46,881.28	27,888.76	18,992.52	40.51

INSPECTION

Date of Assignment:	07/11/2022	Present Location:	Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	07/11/2022	Inspected At:	Goldbell Engineering Pte Ltd (Tuas) 10 Tuas Ave 18 Singapore 638894
Estimated Period of Repair:	7.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Jun 2023)	
Parts:	N/A	MAN TGS 26.400 10.5 D 6X4 BBS (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE3031E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SERVICE DOOR (NPA)	Not Necessary	-	*- F
2	1		*FRONT SERVICE DOOR ASSY	Dented	2,931.36 F	*2,931.36 F
3	2		*RUBBER STOP	Not Necessary	20.70 F	*- F
4	1		*WIND DEFLECTOR RH	Missing	158.71 F	*158.71 F
5	1		*WIND DEFLECTOR RH PRIMED	Missing	447.30 F	*447.30 F
6	1		*GROOVED OVAL HEAD SCREW (12 PCS)	Necessary	31.80 F	*31.75 F
7	1		*BRACKET	Missing	27.94 F	*27.94 F
8	1		*COVERING RH	Missing	15.61 F	*15.61 F
9	1		*BRACKET RH	Missing	164.79 F	*164.79 F
10	1		*PILLAR LINING OUTER (NPA)	Not Necessary	-	*- F
11	1		*PILLAR LINING RH PRIMED	Broken	515.76 F	*515.76 F
12	1		*WATER DEFLECTOR RH	Not Necessary	14.28 F	*- F
13	1		*MIRROR TRIM RH DOOR HINGE	Missing	47.79 F	*47.79 F
14	1		*COVERING	Missing	8.34 F	*8.34 F
15	1		*MOULDED FOAM RH, UPPER	Not Necessary	33.72 F	*- F
16	1		*GROOVED OVAL HEAD SCREW (2 PCS)	Necessary	5.30 F	*5.29 F
17	4		*SNAP NUT	Necessary	15.84 F	*15.84 F
18	1		*STEEL BUMPER CENTRE PART (NPA)	Not Necessary	-	*- F
19	1		*STEEL BUMPER MIDDLE SECTION POWDER-COATED	Not Necessary	2,493.18 F	*- F
20	10		*WASHER	Not Necessary	207.90 F	*- F
21	10		*12 POINT SOCKET	Not Necessary	263.40 F	*- F
22	1		*STEEL BUMPER CORNERS (NPA)	Not Necessary	-	*- F
23	1		*STEEL BUMPER POWDER-COATED RH	Dented	1,913.67 F	*1,913.67 F
24	1		*CARRIER HEADLAMP RH	Missing	289.68 F	*289.68 F
25	1		*PIN	Missing	97.74 F	*97.74 F
26	1		*SUPPORT	Missing	78.12 F	*78.12 F
27	1		*BRACKET HEADLAMP RH	Missing	40.95 F	*40.95 F
28	1		*BRACKET FLASHER RH	Missing	14.53 F	*14.53 F
29	1		*STEEL BUMPER TRIM (NPA)	Not Necessary	-	*- F
30	1		*BUMPER END PANEL RH	Missing	62.95 F	*62.95 F
31	1		*LINE CLIP (2 PCS)	Necessary	5.12 F	*5.11 F
32	1		*STEPWELL LOWER (NPA)	Not Necessary	-	*- F
33	1		*STEPWELL RH	Bent	1,420.38 F	*1,420.38 F
34	1		*STEP SILVER-METALLIC	Bent	272.83 F	*272.82 F
35	1		*HEADLAMPS (NPA)	Not Necessary	-	*- F
36	1		*HEADLAMP RH	Missing	1,016.55 F	*1,016.55 F
37	1		*STEPWELL & MUDGUARD, RH (NPA)	Not Necessary	-	*- F
38	1		*ENTRY MUDGUARD RH	Broken	1,443.10 F	*1,443.10 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*PAN-HEAD SCREW (7 PCS)	Necessary	26.11 F	*26.08 F
40	1		*BRACKET RH	Not Necessary	409.23 F	*- F
41	1		*HEXAGON SCREW (2 PCS)	Necessary	40.04 F	*40.03 F
42	1		*WASHER (2 PCS)	Necessary	20.82 F	*20.83 F
43	1		*MUDGUARD EXTENSION RH	Cut	658.80 F	*658.80 F
44	1		*GROOVED OVAL HEAD SCREW (2 PCS)	Necessary	8.22 F	*8.23 F
45	1		*STEP UPPER SILVER-METALLIC	Missing	173.07 F	*173.07 F
46	1		*STEP CENTRE SILVER-METALLIC	Missing	311.31 F	*311.31 F
47	1		*HEXAGON SCREW (8 PCS)	Necessary	80.24 F	*80.21 F
48	1		*WASHER (8 PCS)	Necessary	83.28 F	*2.65 F
49	1		*HEXAGON NUT (8 PCS)	Necessary	32.88 F	*32.90 F
50	1		*COVER PAINTED	Necessary	12.39 F	*12.39 F
51	1		*STEEL BUMPER RADIATOR GUARD (NPA)	Not Necessary	-	*- F
52	1		*RADIATOR GUARD PAINTED BLACK	Not Necessary	680.01 F	*- F
53	1		*BRACKET LH RADIATOR GUARD	Not Necessary	380.29 F	*- F
54	1		*BRACKET RH RADIATOR GUARD	Not Necessary	380.29 F	*- F
55	4		*HEX COLLAR BOLT	Not Necessary	61.20 F	*- F
56	2		*HEX LOCK BOLT	Not Necessary	21.60 F	*- F
57	1		*FLASHER LATERAL (NPA)	Not Necessary	-	*- F
58	1		*FLASHER LATERAL CLEAR GLASS	Broken	103.11 F	*103.11 F
59	1		*BULB	Necessary	10.89 F	*10.89 F
60	1		*PAN-HEAD SCREW (4 PCS)	Necessary	40.12 F	*40.10 F
61	4		*SPEED NUT	Necessary	25.20 F	*25.20 F
62	1		*TURN SIGNAL, FRONT (NPA)	Not Necessary	-	*- F
63	1		*AUXILIARY HEADLAMP RH, FRONT FLASHER	Broken	322.56 F	*322.56 F
64	1		*SLEEVE FOR HEADLAMP (2 PCS)	Missing	48.72 F	*48.73 F
65	1		*BULB	Necessary	10.89 F	*10.89 F
66	2		*OVAL-HEAD SELF-TAPPING SCREW	Necessary	32.22 F	*32.22 F
67	1		*RD. CONNECTOR SLEEVE HOUSING 4-PIN BLACK	Necessary	16.89 F	*16.89 F
68	1		*FUEL TANK (NPA)	Not Necessary	-	*- F
69	1		*FUEL TANK	Not Necessary	3,505.50 F	*- F
70	1		*SEAL	Not Necessary	4.83 F	*- F
71	1		*DRAIN PLUG	Not Necessary	30.21 F	*- F
72	1		*PROTECTIVE EDGING	Not Necessary	29.43 F	*- F
73	1		*SIDE MARKER LIGHT WITH LIGHT EMITTING DIODE (NPA)	Not Necessary	-	*- F
74	1		*SIDE MARKER LIGHT	Not Necessary	152.05 F	*- F
75	6		*LOCKER WASHER	Not Necessary	48.30 F	*- F
76	2		*LOCKER WASHER	Not Necessary	7.92 F	*- F
77	1		*DISTRIBUTOR PLUG	Not Necessary	22.74 F	*- F
78	1		*END PIECE	Not Necessary	15.90 F	*- F
79	1		*REAR VIEW MIRROR RH DRIVE VEHICLE (NPA)	Not Necessary	-	*- F
80	1		*PAN-HEAD SCREW (14 PCS)	Missing	37.10 F	*37.04 F
81	1		*MIRROR TRIM	Broken	185.35 F	*185.35 F
82	1		*OUTSIDE MIRROR RH DRIVE VEHICLE DOOR	Broken	2,248.44 F	*2,248.44 F
83	1		*MIRROR TRIM RETAINER RH	Missing	39.73 F	*39.73 F
84	1		*MIRROR TRIM RH, UPPER	Missing	50.22 F	*50.22 F
85	1		*RH REAR WHEEL FLARE	Not Necessary	1,700.00 F	*- F
86	1		*RH REAR WHEEL FLARE SUPPORT	Not Necessary	680.00 F	*- F

Supplementary #1

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
87	1		*DOOR WINDOW LEFT (NPA)	Not Necessary	-	*- F
88	1		*WIND-DOWN WINDOW LEFT TINTED	Not Necessary	615.60 F	*- F
89	2		*MOUNTING DOOR GLASS	Not Necessary	45.48 F	*- F
90	2		*CLAMPING FRAME	Not Necessary	12.78 F	*- F
91	2		*PAN-HEAD SCREW	Not Necessary	8.22 F	*- F
92	1		*WINDOW GUIDE REPLACEMENT	Not Necessary	282.73 F	*- F
93	1		*DOOR LEFT SHELL C	Not Necessary	-	*- F
94	1		*DOOR LEFT	Dented	3,927.82 F	*3,927.82 F
95	1		*DOOR HINGE LEFT, UPPER	Not Necessary	690.16 F	*- F
96	1		*RUBBER PAD ELASTOMER	Necessary	9.63 F	*9.63 F
97	1		*TAPPET	Necessary	5.40 F	*5.40 F
98	1		*LOCKER WASHER	Necessary	6.30 F	*6.30 F
99	1		*DOOR HINGE LEFT, LOWER	Not Necessary	369.40 F	*- F
100	1		*HINGE PIN	Necessary	16.11 F	*16.11 F
101	1		*DAMPING PLATE	Not Necessary	73.48 F	*- F
102	1		*CURB MIRROR ELECTRICALLY ACTUATED (NPA)	Not Necessary	-	*- F
103	1		*CURB MIRROR CO-DRIVERS SIDE ELECTRIC	Broken	1,220.26 F	*1,220.26 F
104	1		*MIRROR GLASS HEATABLE	Broken	329.94 F	*329.94 F
105	1		*CYLINDER SCREW (2 PCS)	Necessary	24.38 F	*24.37 F
106	1		*GROMMET WITH HOLE	Necessary	16.80 F	*16.80 F
Supplementary #2						
107	1		*COVERING	Cracked	93.27 F	*93.27 F
Supplementary #3						
108	1		*DOOR CONTROL MODULE, RH	Malfunction	1,879.08 F	*1,879.08 F
F=Franchise part.						
Total Parts (\$\$)					36,434.28	23,092.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COMPANY STICKER (DOOR) (NECESSARY)	480.00	480.00
Sub Total (\$\$)			480.00	480.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN,ETC	New	4,200.00	2,400.00
2	TO TRANSFER DOOR COMPARTMENT / WINDOW GLASS / REGULATOR / LOCK / MECHANISM,ETC	New	700.00	300.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	New	250.00	150.00
4	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	1,750.00	1,400.00
Gross Labour Cost (\$\$)			6,900.00	4,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >