

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011072/UWP3Q2**Date:** 16/11/2022REFERENCE

Insured/Claimant: DRAGONLIM AIR-CON & ENGINEERING PTE LTD

Policy No: DMCVSNW00099222204

Date of Loss: 03/11/2022

Nature of Claim: OD

Claim No: SNM22D207949/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GX3533A**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (M)

Engine No: 1KD2820022

Reg. Date: 11/09/2018 (Man. Year: 2018)

Chassis No: JTFAT35Y90K211396

Colour: Silver

Odometer: 87300 km

Engine Capacity: 2982 cc

Market Value/New Car Price: S\$65,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R12 (D)

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6/6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,673.44	7,061.79	8,611.65	54.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	2,000.00	990.00	33.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,663.44	9,061.79	9,601.65	51.45
Approved Total (Overridden) (S\$)		7,200.00		
- Excess (S\$)	350.00	350.00	0.00	0.00
Nett Amount (S\$)	18,313.44	6,850.00	11,463.44	62.60

INSPECTION

Date of Assignment: 07/11/2022

Date Inspected: 08/11/2022

Inspected At:

Cheng Motor Work Co. (HQ)
1 KAKI BUKIT AVE 6 #01-83
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Nov 2022)		
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GX3533A)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN RUBBER (50%)	Necessary	369.40 FS	*184.70 FS
2	1		*WIPER MOTOR	Not Necessary	887.80 F	*- FL
3	1		*WIPER LINK ASSY	Bent	363.50 F	*363.50 FL
4	1		*WIPER PANEL	Dented	311.80 F	*311.80 FL
5	1		*WIPER PANEL SIDE BRACKET	Cracked	45.49 F	*45.49 FL
6	1		*WIPER NOZZLE	Not Necessary	57.40 F	*- FL
7	1		*WIPER WASHER TANK	Deformed	292.40 F	*266.00 FL
8	1		*FRONT PANEL	Badly Dented	1,781.01 F	*1,291.80 FL
9	1		*EMBLEM DYNA	Necessary	70.51 F	*70.51 FL
10	1		*HEAD LAMP	Cracked	1,296.57 F	*1,272.30 FL
11	1		*FRONT GRILLE	Cracked	595.20 F	*595.20 FL
12	1		*FRONT GRILLE LOGO	Not Necessary	70.50 F	*- FL
13	1		*FRONT BUMPER	Repair	823.35 F	*- FL
14	1		*FRONT STEP GARNISH L/H	Not Necessary	289.80 F	*- FL
15	2		*FRONT BUMPER BRACKET	Not Necessary	460.02 F	*- FL
16	1		*FRONT CORNER PANEL (N/S)	Missing	369.93 F	*369.93 FL
17	1		*FRONT CORNER PANEL SIDE RETAINER (N/S)	Bent	98.90 F	*98.90 FL
18	1		*FRONT DOOR ASSY L/H	Repair	1,507.20 F	*- FL
19	1		*FRONT DOOR PILLAR OUTER	Repair	450.90 F	*- FL
20	2		*FRONT DOOR HINGE	Not Necessary	281.20 F	*- FL
21	1		*FRONT SIDE ROUND MIRROR	Missing	108.46 F	*108.46 FL
22	1		*FRONT SIDE MIRROR WITH STAY ASSY	Missing / Cracked	308.00 F	*308.00 FL
23	1		*FRONT SIDE MIRROR MOTOR	Missing	685.90 F	*685.90 FL
24	1		*FRONT SIDE MIRROR STAY GARNISH	Missing	37.80 F	*37.80 FL
25	1		*FRONT SIDE MIRROR STAY COVER	Missing	47.80 F	*47.80 FL
26	1		*AIR-CON BLOWER UNIT	Cracked	2,674.00 F	*2,674.00 FL
27	1		*AIR-CON COOLING COIL UNIT	Cracked	1,073.60 F	*365.40 FL
28	1		*SIDE MARKER (ROC STICKER N/S)	Necessary	20.00 FS	*20.00 FS
29	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
30	1		*IU BRACKET	Not Necessary	35.00 FS	*- FS
31	1		*FRONT SIDE MIRROR MOTOR ALUMINIUM BRACKET	Cracked	230.00 F	*230.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,673.44	9,347.49
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,285.70
Total Parts (\$\$)	15,673.44	7,061.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FRONT AND REAR KNOCKING ,WELDING ,CUTTING ,REPAIRING AND REPLACEMENT OF PARTS	New	1,000.00	800.00
2	TO SPRAY PAINT ON THE DAMAGE PARTS	New	1,200.00	800.00
3	TO REMOVE /REFIT WINDSCREEN GLASS	New	150.00	80.00
4	TO REMOVE/REFIT DASHBOARD	New	280.00	200.00
5	TO REMOVE /REFIT AIRCON SYSTEM & REFILL GAS	New	280.00	100.00
6	TO CHECKING WIRING	New	80.00	20.00
Gross Labour Cost (\$\$)			2,990.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >