LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Adeline Chng Pei Wen Date: 08 Nov 2022 Attn:

Preliminary Advice

Vehicle No : GBH3720U **Accident Date** : 02/11/2022

Make : TOYOTA HIACE Policy No.

DMCVSNW00094472200

Assignment Date : 07/11/2022 Excess : S\$450.00

Date of Inspection : 7/11/2022 Est. Duration of Repair : 6

Inspection At : JIN AUTO SERVICES PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 6,944.03 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 6,049.03 |
| Check Items (Estimated) | :S\$ | 895.00 |
| Total | :S\$ | 6,944.03 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 56,000.00 COF / PARF Rebate :S\$ 16,585.00

Salvage Value :S\$

Margin for Repair :S\$ 39,415.00

Remarks

| (X) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly |
|-------|---|
| | let us have your authorisation. |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advise amount (Revised & Check items) stated are subject (X) to consistency check, part prices and labour cost.