

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EGI22011075/UQY3E2**Date:** 12/12/2022**REFERENCE**

Insured/Claimant:	OXF INTERNATIONAL PTE LTD	Policy No:	DMPG21014585
Date of Loss:	26/10/2022	Nature of Claim:	OD
		Claim No:	CDMPG22002301

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT6777E		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)	Engine No:	27492031183737
Reg. Date:	20/12/2017 (Man. Year: 2017)	Chassis No:	WDC2539462F320172
Colour:	Silver	Odometer:	67460 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,072.60	4,389.00	6,683.60	60.36
Miscellaneous Items	720.00	0.00	720.00	100.00
Labour	3,200.00	1,000.00	2,200.00	68.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,992.60	5,389.00	9,603.60	64.06
- Excess (S\$)	0.00	700.00	-700.00	
(S\$)	14,992.60	4,689.00	10,303.60	68.72
+ GST 7.00/7.00% (S\$)	1,049.48	328.23	721.25	68.72
Nett Amount (S\$)	16,042.08	5,017.23	11,024.85	68.72

INSPECTION

Date of Assignment:	07/11/2022	Present Location:	Automobile Integrated Management Pte Ltd (HQ) Automobile Integrated Management Pte Ltd (HQ)
Date Inspected:	09/11/2022	Inspected At:	23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2022)
Parts: M1-SUV	MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLT6777E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER) (WCP)	Torn	680.00 F	*680.00 F
2	1		*REAR BUMPER (LOWER) (WCP)	Grazed	550.00 F	*550.00 F
3	1		*REAR BUMPER CHROME (CENTER) (WCP)	Cracked	350.00 F	*350.00 F
4	2		*REAR BUMPER REFLECTOR (WCP)	Not Necessary	76.00 F	*- F
5	1		*REAR BUMPER TOWING COVER (WCP)	Not Necessary	45.00 F	*- F
6	2		*REAR BUMPER EXHAUST CHROME (WCP)	Bent	370.00 F	*740.00 F
7	2		*REAR BUMPER EXHAUST CHROME BRACKET (WCP)	Cracked	180.00 F	*180.00 F
8	1		*REAR BUMPER SENSOR (4PCS)(WCP)	Shorted (2Pcs Only)	740.00 F	*370.00 F
9	1		*REAR BUMPER SENSOR HOLDER (6PCS)(WCP)	Necessary (2Pcs Only)	240.00 F	*180.00 F
10	1		*REAR BUMPER SENSOR WIREHARNES (WCP)	Not Necessary	420.00 F	*- F
11	2		*REAR BUMPER SIDE RETAINER (WCP)	Cracked	180.00 F	*360.00 F
12	2		*REAR BUMPER CENTER TOP BEAM (WCP)	Not Necessary	250.00 F	*- F
13	1		*REAR BUMPER CENTER LOWER BEAM (WCP)	Not Necessary	145.00 F	*- F
14	2		*REAR BUMPER LOWER BRACKET (WCP)	Not Necessary	130.00 F	*- F
15	1		*REAR BUMPER REINFORCEMENT (WCP)	Bent	580.00 F	*580.00 F
16	2		*TAILLAMP (WCP)	Not Necessary	840.00 F	*- F
17	2		*REAR FENDER COWLING (WCP)	Not Necessary	310.00 F	*- F
18	2		*REAR WHEEL ARCED GARNISH (WCP)	Not Necessary	330.00 F	*- F
19	1		*TAILGATE WEATHER STRIP (WCP)	Not Necessary	205.00 F	*- F
20	1		*REAR END PANEL (WCP)	Repair	850.00 F	*- F
21	1		*REAR END PANEL TOP GARNISH (WCP)	Not Necessary	225.00 F	*- F
22	1		*REAR FLOOR TOP COVER BOARD (WCP)	Not Necessary	650.00 F	*- F
23	1		*REAR EXHAUST BOX C/W CENTER (WCP)	Not Necessary	1,250.00 F	*- F
24	2		*REAR EXHAUST INSULATOR (WCP)	Repair	330.00 F	*- F
25	4		*REAR EXHAUST MOUNTING (WCP)	Not Necessary	140.00 F	*- F

F=Franchise part.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	10,066.00	3,990.00
					+ Margin on L,N Items 10.00/10.00% (\$)	1,006.60	399.00
					Total Parts (\$)	11,072.60	4,389.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE (NOT NECESSARY)	50.00	0.00
2	1	REAR BUMPER CLIP (SET) (NOT NECESSARY)	60.00	0.00
3	1	REAR END PANEL INNER GARNISH CLIP (SET) (NOT NECESSARY)	60.00	0.00
4	1	REAR END PANEL INSULATION SEAL (NOT NECESSARY)	250.00	0.00
5	1	REAR FENDER COWLING CLIP (SET) (NOT NECESSARY)	80.00	0.00
6	1	REAR FENDER INNER TRIM CLIP (SET) (NOT NECESSARY)	80.00	0.00
7	1	REAR WHEEL ARCED GARNISH CLIP (SET) (NOT NECESSARY)	80.00	0.00
8	1	TAILLAMP CLIPS (SET) (NOT NECESSARY)	60.00	0.00
Sub Total (\$)			720.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,000.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	400.00
3	TUFF COAT	New	200.00	0.00
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	200.00	60.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	40.00
6	REMOVE AND REFIX REAR EXHAUST PIPE	New	120.00	0.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	New	350.00	0.00
Gross Labour Cost (\$)			3,200.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >