

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: *SL7 6777E*  
 at Workshop m/s: *AIM*  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: *\$ 700*  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

Veh No: *SL76777E* Yr Regn: *20/12/17*  
 Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or *CA/ AMGLINE*  
 Make: *Mer Benz GLC250* c.c. *1991*  
 Colour: *Silver* A/C: *Insured / Std / NI / NA*  
 Sp. Reading: *67460* T/Radio: *Insured / Std / NI / NA*  
 Eng/No: \_\_\_\_\_  
 C/No: *WDC 2539462 F.3 20172*  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or  
 Brake:  In order / Jammed / Leaked / Burnt or  
 Modi:  Nil / S/Rim / STD A/Rim or

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Tyre Size: F: *235/55-19*  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU  PIR / SUMI /  
 TOYO / YOKO or  
 Front *7* mm Rear *7* mm  
 R/Bal. *7* mm L/Bal. *7* mm  
 L/Bal. *7* mm  
 D.O.A. *26/10/22* D.O.I. *09/11/22*  
 Survey held at \_\_\_\_\_

Bal. or Market Value: *\$ 140k.*  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: *4* days Res.: Yes or No  
 Lum Sum: *1.3.1* % 3 Val.: Yes or No  
 CA / REV  REP / 24 HRS *C 5978*  
 Vehicle: IN / OUT  
 Date: \_\_\_\_\_ Person Contacted: *LTA 6488*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
*Rear*  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>2024k</i>
	<i>No second hand parts repairer went repair P/P</i>
	<i>P/P \$ 5389 (Red \$ 10248.60, 66%)</i>

Date/Time, File Pass to?  : Preli. Report  : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Days Of Repair: *4*  
 Resurvey No. of Trip: *2*  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ ) S + RS, SI  
 : Interview (\$ ) Photos  
 : Tech. Invs (\$ ) Others  
 : Weekend (\$ )

Report Format: *MER-00*  
 Lump Sum / I.B.I.: (\$ *5389*)

TOTAL \_\_\_\_\_



Co. & G.S.T. Reg no. 201605297G  
 Workshop: 23 Kaki Bukit Ave 4 #04-01 (South Wing)  
 Singapore 415933  
 Email: automim.claim@gmail.com Tel: 9119 8371  
 Website: www.aimgarage.com.sg

**ESTIMATE**

Our Ref: AC2022074/TP

Vehicle number: SLT6777E

Vehicle Made & Model: MERC BENZ GLC250

Qty	List Items	Amount \$
1	1 REAR BUMPER (UPPER) <i>Tom</i>	\$ 680.00
2	1 REAR BUMPER (LOWER) <i>green</i>	\$ 550.00
3	1 REAR BUMPER CHROME (CENTER) <i>one</i>	\$ 350.00
4	2 REAR BUMPER REFLECTOR <i>17</i>	\$ 76.00 <i>X</i>
5	1 REAR BUMPER TOWING COVER <i>17</i>	\$ 45.00 <i>X</i>
* 6	2 REAR BUMPER EXHAUST CHROME <i>Bent @ 370 x 2 = 740</i>	\$ <del>370.00</del> <i>740</i>
7	2 REAR BUMPER EXHAUST CHROME BRACKET <i>one</i>	\$ 180.00
8	4 REAR BUMPER SENSOR <i>Slud @ 185 x 2 = 370</i>	\$ 740.00 <i>2 pcs</i>
9	6 REAR BUMPER SENSOR HOLDER <i>mer @ 90 x 2 = 180</i>	\$ 240.00
10	1 REAR BUMPER SENSOR WIREHARNES <i>17</i>	\$ 420.00 <i>X</i>
* 11	2 REAR BUMPER SIDE RETAINER <i>@ 180 x 2 = 360 one</i>	\$ <del>180.00</del> <i>360</i>
12	2 REAR BUMPER CENTER TOP BEAM <i>17</i>	\$ 250.00 <i>X</i>
13	1 REAR BUMPER CENTER LOWER BEAM <i>17</i>	\$ 145.00 <i>X</i>
14	2 REAR BUMPER LOWER BRACKET <i>17</i>	\$ 130.00 <i>X</i>
15	1 REAR BUMPER REINFORCEMENT <i>Bent</i>	\$ 580.00
16	2 TAILLAMP <i>17</i>	\$ 840.00 <i>X</i>
17	2 REAR FENDER COWLING <i>17</i>	\$ 310.00 <i>X</i>
18	2 REAR WHEEL ARCED GARNISH <i>17</i>	\$ 330.00 <i>X</i>
19	1 TAILGATE WEATHER STRIP <i>17</i>	\$ 205.00 <i>X</i>
20	1 REAR END PANEL <i>17</i>	\$ 850.00 <i>X</i>
21	1 REAR END PANEL TOP GARNISH <i>17</i>	\$ 225.00 <i>X</i>
22	1 REAR FLOOR TOP COVER BOARD <i>17</i>	\$ 650.00 <i>X</i>
23	1 REAR EXHAUST BOX C/W CENTER <i>17</i>	\$ 1,250.00 <i>X</i>
24	2 REAR EXHAUST INSULATOR <i>R</i>	\$ 330.00 <i>X</i>
25	4 REAR EXHAUST MOUNTING <i>17</i>	\$ 140.00 <i>X</i>

Sub-total \$ 10,066.00  
 Cost +10% \$ 1,006.60  
 Total List \$ 11,072.60

*Not Authorized  
 Linc  
 memo  
 9/11/22  
 Excess?  
 Hdy's*

*Plp @ 5389 /  
 before painting*

*1-3990  
 + 102  
 4389  
 1000  
 5389*

Vehicle number:SLT6777E

Vehicle Made & Model: MERC BENZ GLC250

**Special Nett Item**

1	FRONT NUMBER PLATE	11	\$	50.00	X
1	REAR BUMPER CLIP (SET)	11	\$	60.00	X
2	TAILLAMP CLIPS (SET)	11	\$	60.00	X
2	REAR FENDER COWLING CLIP (SET)	11	\$	80.00	X
2	REAR FENDER INNER TRIM CLIP (SET)	11	\$	80.00	X
2	REAR WHEEL ARCED GARNISH CLIP (SET)	11	\$	80.00	X
1	REAR END PANEL TOP GARNISH CLIP (SET)	11	\$	40.00	X
1	REAR END PANEL INSULATION SEAL	11	\$	250.00	X
1	REAR END PANEL INNER GARNISH CLIP (SET)	11	\$	60.00	X
			\$	<u>760.00</u>	

**Labour charges**

PANEL BEATING, REMOVAL AND REPLACING PARTS	\$	1,000.00	500
TO SPRAY PAINT AFFECTED AREA TUFF COAT	\$	1,000.00	400
REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	11 \$	200.00	X
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	200.00	60
REMOVE AND REFIX REAR EXHAUST PIPE	11 \$	80.00	40
REAR CHASSIS ALIGNMENT	11 \$	120.00	X
	11 \$	250.00	X
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	11 \$	350.00	X
	\$	<u>3,200.00</u>	

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$**

**\$ 15,032.60**

1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**SURPASS AUTO PARTS SUPPLIES PTE LTD**  
 10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175  
 Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com  
 Co & Gst Reg No: 199904808E

Doc SUDMWS10/04/10/2022

CASH DBS

**CASH SALES**  
 No. : CS-019767  
 Date : 09/11/2022  
 Page : 1 of 2

E/N	Item No.	Description	Qty	U/ Price	Amount
	A25388516019999	AMG REAR TRIM BUMPER 9**	1	680.00	680.00
	A2538850300	AMG REAR TRIM BUMPER LOWER	1	550.00	550.00
	A2538851000	AMG REAR BUMPER MOULDING 2538850701	1	350.00	350.00
	A2054900300	2538850701 TAIL PIPE AMG LH GLC & C 2054901127	1	* 370.00	370.00
	A2054901227	2538850701 TAIL PIPE AMG RH GLC	1	* 370.00	370.00
	A2538852501	2538850701 PIPE BASIC MOUNTING	1	90.00	90.00
	A2538852601	2538850701 PIPE BASIC MOUNTING	1	90.00	90.00
	A00090555049999	DISTANCE SENSOR	2	185.00	370.00
	A1718850014	BRACKET SENSON	2	90.00	180.00
	A2538800512	MOUNTING RAIL	1	* 180.00	180.00
	A2538800612	MOUNTING RAIL	1	* 180.00	180.00
	A2536102101	REAR CROSS MEMBER	1	580.00	580.00

AiM Pte Ltd  
 (Automobile Integrated Management)  
 23 Kaki Bukit Ave 4  
 Kaki Bukit Vicom singapre 415933

**SURPASS AUTO PARTS SUPPLIES PTE LTD**  
 10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175  
 Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com  
 Co & Gst Reg No: 199904808E

15/11/2022 16:38:30

CASH DBS

**CASH SALES**  
 No. : CS-019767  
 Date : 09/11/2022  
 Page : 2 of 2

E/N	Item No.	Description	Qty	U/ Price	Amount
		#04-01			

Sub Total 3,990.00  
 GST 7% 279.30  
 Total 4,269.30

Customer's Signature