

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS22011076/TVY3M4**Date:** 29/11/2022**REFERENCE**

Insured/Claimant: KOH BACK YONG DESMOND Policy No: SP2002536015-01
Date of Loss: 03/11/2022 Nature of Claim: OD Claim No: 202222007921

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF2328G**
Make & Model: TOYOTA HARRIER, 2.0 M GRADE (A) Engine No: 8ARZ132352
Reg. Date: 27/09/2018 (Man. Year: 2018) Chassis No: JTEZB3GH90J002723
Colour: Blue Odometer: 0 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:
Front Left Side: 6 mm Rear Left Side: 6 mm
Front Right Side: 6 mm Rear Right Side: 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,372.20	9,716.20	2,656.00	21.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	2,200.00	1,860.00	45.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,432.20	11,916.20	4,516.00	27.48
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	16,432.20	11,416.20	5,016.00	30.53
+ GST 7.00/7.00% (S\$)	1,150.26	799.13	351.13	30.53
Nett Amount (S\$)	17,582.46	12,215.33	5,367.13	30.53

INSPECTION

Date of Assignment: 04/11/2022 Present Location: Falcon-Air Auto Services Pte Ltd (Sin Ming)
Date Inspected: 07/11/2022 Inspected At: Falcon-Air Auto Services Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-06, Sin Ming Autocare
Singapore 575721
Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2022)

Parts: M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF2328G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet (WCP)	Bent	440.00 F	*440.00 F
2	1		*Bonnet Chrome (WCP)	Not Necessary	180.00 F	*- F
3	8		*Bonnet Insulator Clip	Not Necessary	16.00 FS	*- FS
4	2		*Bonnet Hinge (WCP)	Not Necessary	100.00 F	*- F
5	1		*Radiator Grille Assy (WCP)	Not Necessary	360.00 F	*- F
6	1		*RH Headlamp (HID) (WCP)	Cracked	2,150.00 F	*2,150.00 F
7	1		*RH Headlamp Bracket (WCP)	Cracked	45.00 F	*45.00 F
8	1		*Front Bumper (WCP)	Deformed	290.00 F	*290.00 F
9	10		*Front Bumper Clip	Necessary	20.00 FS	*20.00 FS
10	1		*LH Front Bumper Side Retainer (WCP)	Not Necessary	50.00 F	*- F
11	1		*RH Front Bumper Side Retainer (WCP)	Deformed	50.00 F	*50.00 F
12	1		*Front Bumper Lower Grille (WCP)	Deformed	170.00 F	*160.00 F
13	1		*Front Bumper Sponge - Centre (WCP)	Cracked	75.00 F	*75.00 F
14	1		*Front Bumper Sponge - RH (WCP)	Deformed	45.00 F	*45.00 F
15	1		*Front Bumper Lower Lip (WCP)	Cut	165.00 F	*165.00 F
16	1		*Front Bumper Parking Sensor - RH Outer (WCP)	Not Working	185.00 F	*185.00 F
17	1		*Front Bumper Parking Sensor Holder - RH Outer (WCP)	Necessary	28.00 F	*28.00 F
18	1		*Front Bumper Running Lamp - RH (WCP)	Cracked	380.00 F	*380.00 F
19	1		*RH Fog Lamp (WCP)	Cracked	145.00 F	*145.00 F
20	1		*Front Support Panel (WCP)	Not Necessary	400.00 F	*- F
21	1		*RH Front Fender (WCP)	Bent	335.00 F	*335.00 F
22	1		*RH Front Fender Shield (WCP)	Deformed	175.00 F	*175.00 F
23	10		*RH Front Fender Shield Clip	Necessary	20.00 FS	*20.00 FS
24	1		*RH Wing Mirror Cover (WCP)	Repair	65.00 F	*- F
25	1		*Wiper Washer Tank (WCP)	Deformed	85.00 F	*85.00 F
26	1		*Wiper Washer Tank Neck (WCP)	Not Necessary	55.00 F	*- F
27	1		*RH Front Tyre - Dunlop 235/55R18	Cut	340.00 FS	*340.00 FS
28	1		*RH Front Rim - 18	Dented	1,150.00 FS	*1,150.00 FS
29	1		*RH Front Shock Absorber (WCP)	Bent	350.00 F	*350.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*RH Front Shock Absorber Bearing (WCP)	Necessary	25.00 F	*25.00 F
31	1		*RH Front Shock Absorber Mounting (WCP)	Necessary	85.00 F	*85.00 F
32	1		*RH Front Knuckle Arm (WCP)	Bent	225.00 F	*225.00 F
33	1		*RH Front Lower Arm (WCP)	Bent	210.00 F	*210.00 F
34	1		*RH Front Linkage (WCP)	Bent	60.00 F	*60.00 F
35	1		*Front Axle (WCP)	Not Necessary	1,180.00 F	*- F
36	1		*Steering Rack (WCP)	Bent	780.00 F	*780.00 F
37	1		*Tie Rod End (WCP)	Bent	50.00 F	*50.00 F
38	1		*RH Front Wheel Hub w/Bearing (WCP)	Bent	250.00 F	*250.00 F
Supplementary #1						
39	1		*ball joint (WCP)	Bent	80.00 F	*80.00 F
40	1		*RH headlamp module (WCP)	Distorted	390.00 F	*390.00 F
41	1		*fender inner seal (WCP)	Necessary	40.00 F	*40.00 F
42	1		*RH side panel beam (WCP)	Bent	70.00 F	*70.00 F
43	1		*RH front fender bracket (WCP)	Bent	74.00 F	*74.00 F
F=Franchise part. S=SpcNett.						
					Sub Total (S\$)	11,388.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	984.20
					Total Parts (S\$)	12,372.20
						8,972.00
						744.20
						9,716.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To check wiring and focus headlamp	New	80.00	40.00
2	To remove/replace undercarriage and front axle	New	350.00	150.00
3	To install steering rack and reprogramming	New	350.00	150.00
4	Chassis alignment	New	300.00	0.00
5	Computerise wheel alignment	New	120.00	80.00
6	To transfer new tyre to new rim and balancing	New	60.00	30.00
7	To remove/replace necessary parts, repair RH front fender inner panel, cut out accident damage parts, reweld new panel, alignment	New	1,000.00	750.00
8	To spray paint bonnet, front bumper, headlamp panel, RH front fender, fender inner panel, RH front door, RH wing mirror cover	New	1,800.00	1,000.00
Gross Labour Cost (\$\$)			4,060.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >