



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD
CO. REG. No.: 1995-01140-D

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002536015-01	Date of Loss:	03/11/2022
Vehicle Reg. No.:	SMF2328G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KOH BACK YONG DESMOND		
Make/Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Vehicle Reg. Date:	27/09/2018
Vehicle Colour:	BLACK		
Engine No:	8ARZ132352	Chassis No:	JTEZB3GH90J002723
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO SAS		
Remarks:	VEHICLE IS IN W/SHP. PLEASE ARRANGE FOR VEHICLE SURVEY.		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	11,652.80
Miscellaneous Items	0.00
Labour	4,060.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	15,712.80
+ GST 7.00% (\$\$)	1,099.90
Nett Amount (\$\$)	16,812.70

This claim is handled by: GAIL NG

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Nov 2022)

Parts: M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SMF2328G/04/11/2022 17:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet	0.00	0.00	*440.00 F bt ✓
2	1		*Bonnet Chrome	0.00	0.00	*180.00 F ?
3	8		*Bonnet Insulator Clip	0	0.00	*16.00 FS x
4	2		*Bonnet Hinge	0.00	0.00	*100.00 F x
5	1		*Radiator Grille Assy	0.00	0.00	*360.00 F x
6	1		*RH Headlamp (HID)	0.00	0.00	*2,150.00 F con ✓
7	1		*RH Headlamp Bracket	0.00	0.00	*45.00 F ?
8	1		*Front Bumper	0.00	0.00	*290.00 F de ✓
9	10		*Front Bumper Clip	0	0.00	*20.00 FS ne ✓
10	1		*LH Front Bumper Side Retainer	0.00	0.00	*50.00 F x
11	1		*RH Front Bumper Side Retainer	0.00	0.00	*50.00 F de ✓
12	1		*Front Bumper Lower Grille	0.00	0.00	*170.00 F ?
13	1		*Front Bumper Sponge - Centre	0.00	0.00	*75.00 F ?
14	1		*Front Bumper Sponge - RH	0.00	0.00	*45.00 F de ✓
15	1		*Front Bumper Lower Lip	0.00	0.00	*165.00 F m ✓
16	1		*Front Bumper Parking Sensor - RH Outer	0.00	0.00	*185.00 F R ✓
17	1		*Front Bumper Parking Sensor Holder - RH Outer	0.00	0.00	*28.00 F ne ✓
18	1		*Front Bumper Running Lamp - RH	0.00	0.00	*380.00 F con ✓
19	1		*RH Fog Lamp	0.00	0.00	*145.00 F ?
20	1		*Front Support Panel	0.00	0.00	*400.00 F ?
21	1		*RH Front Fender	0.00	0.00	*335.00 F bt ✓
22	1		*RH Front Fender Shield	0.00	0.00	*175.00 F de ✓
23	10		*RH Front Fender Shield Clip	0	0.00	*20.00 FS ne ✓
24	1		*RH Wing Mirror Cover	0.00	0.00	*65.00 F R ✓
25	1		*Wiper Washer Tank	0.00	0.00	*85.00 F de ✓
26	1		*Wiper Washer Tank Neck	0.00	0.00	*55.00 F ?
27	1		*RH Front Tyre - Dunlop 235/55R18	0	0.00	*340.00 FS ?
28	1		*RH Front Rim - 18	0	0.00	*1,150.00 FS dd ✓
29	1		*RH Front Shock Absorber	0.00	0.00	*350.00 F bt ✓
30	1		*RH Front Shock Absorber Bearing	0.00	0.00	*25.00 F ne ✓
31	1		*RH Front Shock Absorber Mounting	0.00	0.00	*85.00 F ne ✓
32	1		*RH Front Knuckle Arm	0.00	0.00	*225.00 F bt ✓
33	1		*RH Front Lower Arm	0.00	0.00	*210.00 F bt ✓
34	1		*RH Front Linkage	0.00	0.00	*60.00 F ?
35	1		*Front Axle	0.00	0.00	*1,180.00 F ?
36	1		*Steering Rack	0.00	0.00	*780.00 F ?
37	1		*Tie Rod End	0.00	0.00	*50.00 F ?
38	1		*RH Front Wheel Hub w/Bearing	0.00	0.00	*250.00 F bt ✓

F=Franchise part, S=SpcNett.

Sub Total (\$)	10,734.00
+ Margin on L,N Items 10.00% (\$)	918.80
Total Parts (\$)	11,652.80

Falcon-Air Auto Services Pte Ltd/SMF2328G/04/11/2022 17:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To check wiring and focus headlamp	New	80.00 40
2	To remove/replace undercarriage and front axle	New	? 350.00 150
3	To install steering rack and reprogramming	New	? 350.00 150
4	Chassis alignment	New	300.00 200?
5	Computerise wheel alignment	New	120.00 80
6	To transfer new tyre to new rim and balancing	New	60.00 30
7	To remove/replace necessary parts, repair RH front fender inner panel, cut out accident damage parts, reweld new panel, alignment	New	1,000.00 750
8	To spray paint bonnet, front bumper, headlamp panel, RH front fender, fender inner panel, RH front door, RH wing mirror cover	New	1,800.00 1000
Gross Labour Cost (S\$)			4,060.00

Falcon-Air Auto Services Pte Ltd/SMF2328G/04/11/2022 17:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110

Website: www.falconair.com.sg Email: email@falconair.com.sg

Taufik 97495749
not advise 7/4/22.
EX500
P/P resurvey before paint.
taufik@lkhands.com
6 days - 07 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: