

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011085/ANP3Q2**Date:** 11/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00032592201
Claimant Vehicle No :	SKP6396D	Insured Vehicle No :	SMW2365J
Date of Loss:	26/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207822/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP6396D		
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Engine No:	B012J785N13B16A
Reg. Date:	26/09/2014 (Man. Year: 2014)	Chassis No:	WBA3A12000J722167
Colour:	White	Odometer:	149063 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,659.65	2,420.75	6,238.90	72.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,620.00	1,320.00	4,300.00	76.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,279.65	3,740.75	10,538.90	73.80
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	14,279.65	3,000.00	11,279.65	78.99

INSPECTION

Date of Assignment:	07/11/2022	
Date Inspected:	07/11/2022	Inspected At: Averment Auto Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #07-16 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2023)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP6396D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,420.00 FL	*1,420.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	65.00 FL	*65.00 FL
3	1		*REAR BUMPER CORNER RETAINER RH	Not Necessary	13.00 FL	*- FL
4	1		*REAR FENDER RH	Repair	2,010.00 FL	*- FL
5	1		*REAR FENDER INNER SHIELD RH	Not Necessary	856.00 FL	*- FL
6	1		*REAR SUSPENSION KNUCKLE ARM RH	Not Necessary	1,350.00 FL	*- FL
7	1		*REAR SUSPENSION KNUCKLE ARM BEARING RH	Not Necessary	212.00 FL	*- FL
8	1		*REAR SUSPENSION LOWER ARM RH	Not Necessary	156.00 FL	*- FL
9	1		*REAR SUSPENSION TRAILING ARM RH	Not Necessary	140.00 FL	*- FL
10	1		*REAR SUSPENSION THRUST ARM RH	Not Necessary	390.00 FL	*- FL
11	1		*REAR SUSPENSION TORSIN ARM RH	Not Necessary	335.00 FL	*- FL
12	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
13	1		*REAR FENDER SEALANT RH	Not Necessary	120.00 FS	*- FS
14	1		*REAR FENDER INNER SHIELD CLIPS SET RH	Not Necessary	80.00 FS	*- FS
15	1		*REAR SPORT RIM RH	Cut	1,080.00 FS	*980.00 FS
16	1		*REAR TYRE RH	Not Necessary	680.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,007.00	2,495.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	347.35	74.25
Total Parts (\$\$)	8,659.65	2,420.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,500.00	500.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,000.00	500.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	150.00	40.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	250.00	30.00
5	TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	New	580.00	0.00
6	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	New	220.00	0.00
7	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	230.00	50.00
8	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	New	480.00	0.00
9	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	240.00	80.00
10	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	220.00	0.00
11	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	550.00	120.00
12	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	200.00	0.00
Gross Labour Cost (S\$)			5,620.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >