

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III22011087/UPA3Q2**Date:** 17/02/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MPC0005175  
**Claimant Vehicle No :** SLQ7792U **Insured Vehicle No :** SKS4883L  
 Date of Loss: 04/11/2022 Nature of Claim: TP Claim No: MPC2022D0008379

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLQ7792U**  
 Make & Model: HONDA VEZEL, 1.5 X HYBRID CVT (A) Engine No: LEB5948299  
 Reg. Date: 21/07/2017 (Man. Year: 2017) Chassis No: RU31248283  
 Colour: Brown Odometer: 123033 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,896.04	2,572.68	4,323.36	62.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	1,820.00	1,970.00	51.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,686.04</b>	<b>4,392.68</b>	<b>6,293.36</b>	<b>58.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,686.04</b>	<b>3,500.00</b>	<b>7,186.04</b>	<b>67.25</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,907.45</b>		

**INSPECTION**

Date of Assignment: 07/11/2022  
 Date Inspected: 08/11/2022 Inspected At: Zoom Autowerks Pte Ltd (HQ)  
 130 Bedok Reservoir Road, Eunos Spring, #08-1339  
 Singapore 470130  
 Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2022)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ7792U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	121.80 FL	*110.00 FL
2	1		*REAR TAILGATE	Badly Dented	1,287.60 FL	*953.00 FL
3	1		*REAR TAILGATE INNER TRIM BOARD	Deformed / Cracked	225.00 FL	*225.00 FL
4	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	32.00 FL	*- FL
5	1		*REAR TAILGATE LOCK	Twisted / Damaged	269.50 FL	*180.20 FL
6	1		*REAR TAILGATE LOCK CATCH	Not Necessary	55.00 FL	*- FL
7	1		*REAR TAILGATE LOGO	Not Necessary	40.30 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	185.50 FL	*- FL
9	1		*REAR TAILGATE RUBBER	Twisted	227.00 FL	*162.30 FL
10	1		*REAR TAILGATE VEZLE EMBLEM	Necessary	56.20 FL	*56.20 FL
11	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	62.50 FL	*62.50 FL
12	2		*REAR TAILLAMPS	Not Necessary	1,390.00 FL	*- FL
13	1		*REAR END PANEL	Repair	585.80 FL	*- FL
14	1		*REAR END PANEL INNER GARNISH	Twisted	160.50 FL	*160.50 FL
15	1		*REAR BUMPER	Dented / Deformed	950.60 FL	*762.30 FL
16	2		*REAR BUMPER -SIDE	Repair	450.60 FL	*- FL
17	2		*REAR BUMPER REFLECTORS	Not Necessary	303.80 FL	*- FL
18	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	101.80 FL	*- FL
19	1		*REAR FLOOR BOARD (TOP TRAY )	Cracked	187.60 FL	*187.60 FL
20	1		*REAR FLOOR PANEL	Repair	1,145.70 FL	*- FL
21	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
22	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
23	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
24	1		*REAR REVERSE SENSOR BUZZER	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,463.80</b>	<b>3,144.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,567.76	571.92

<b>Total Parts (\$\$)</b>	<b>6,896.04</b>	<b>2,572.68</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	120.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING	New	80.00	30.00
7	PANEL BEATING	New	1,600.00	580.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	880.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,790.00</b>	<b>1,820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >