



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 8397H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR MUDFLAP	DEFORMED	68.00	68.00
1	TAILLAMP	CRACKED	115.00	115.00
1	REAR RH SIGNAL LAMP	CRACKED	34.00	34.00
1	REAR EXHAUST PIPE	BENT	490.00	490.00
1	REAR EXHAUST PIPE HEAT SHIELD	CUT	110.00	110.00
1	REAR EXHAUST PIPE END PROTECTOR	CRACKED	45.00	45.00
1	REAR RH FOOTREST	CUT	35.00	35.00
1	REAR RH FOOTREST BRACKET	BENT	108.00	108.00
1	REAR RH SIDE FAIRING	TO REPAIR SEE LABOUR	120.00	-
1	REAR FAIRING HANDLE	NOT NECESSARY	60.00	-
1	CENTRE FAIRING (LOWER) RH	TO REPAIR SEE LABOUR	78.00	-
1	FRONT RH FOOTREST	CUT	35.00	35.00
1	ENGINE COVER	CUT	85.00	85.00
1	FRONT FAIRING (RH)	CUT	185.00	185.00
1	FRONT RH SIGNAL LAMP	CUT	42.00	42.00
1	BALANCER RH	CUT	28.00	28.00
1	HANDLE BAR RH	BENT	55.00	55.00
1	FRONT RH WING MIRROR	CUT	45.00	45.00
1	FRONT RH LOWER	CUT	40.00	40.00
1	HEADLAMP	NOT NECESSARY	285.00	-
1	HEADLAMP COWLING	CUT	155.00	155.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	70.00	-
1	FRONT FORK ASSY	TO REPAIR SEE LABOUR	480.00	-
1	STEERING UNDER BRACKET	NOT NECESSARY	160.00	-
1	STEERING CONE AND BEARING	NECESSARY	55.00	55.00
1	REAR SWING ARM	BENT	310.00	310.00
	LESS 10% DISCOUNT		-	-204.00
			3,293.00	1,836.00

Report Ref No. CS/AGI22011094/Any3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	25.00	25.00
1	FRONT FORK OIL (SN)	NECESSARY	40.00	40.00
1	REAR BOX (SN)	CUT	280.00	250.00
1	REAR BOX BRACKET (SN)	BENT	200.00	200.00
1	STICKER (SN)	NECESSARY	100.00	50.00
			645.00	565.00
	<u>LABOUR</u>			
	LABOUR.INCLUSIVE OF THE REPAIR OF REAR RH SIDE FAIRING,CENTRE FAIRING (LOWER) RH,FRONT FENDER AND FRONT FORK ASSY .		400.00	200.00
	SPRAY PAINTING.		400.00	200.00
	WIRING.		50.00	30.00
	TO STRAIGHTEN BODY CHASSIS.		280.00	200.00
	TOWING FEES.		40.00	40.00
			1,170.00	670.00
GRAND TOTAL			5,108.00	3,071.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/AGI22011094/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.