



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 1070J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH SIDE MIRROR	SERVICEABLE	350.00	-
1	LH SIDE MIRROR COVER	DENTED	185.00	185.00
	LESS 10% DISCOUNT		-	-18.50
			535.00	166.50
	<u>LABOUR</u>			
	TO REMOVE AND INSTALL LH SIDE MIRROR .		350.00	180.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		100.00	20.00
	TO SPRAY PAINT LH SIDE MIRROR .		150.00	80.00
			600.00	280.00
GRAND TOTAL			1,135.00	446.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				350.00

Report Ref No. CS/FCI22011097/Kvy3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.