



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22011097/Kvy3q2 Date: 05/12/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 3T	Veh. Inspected	GBK 1070J	
Policy No.	D-19094111MFB	Coverage (\$)	0.00	
Claim No.	D22003467MFBP	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	07/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	OPEL VIVARO (M)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	W0VF7G608JV606176	Colour	METALLIC GREY	
Odometer	74619 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R15	TOURADOR	7 mm	
L/H Front Tyre	215/60 R15	TOURADOR	7 mm	
R/H Rear Tyre	215/60 R15	TOURADOR	9 mm	
L/H Rear Tyre	215/60 R15	TOURADOR	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S SIDE MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2022	Inspection Date	17/11/2022	
Survey held at	GOLDBELL @ AMK 5035 ANG MO KIO INDUSTRIAL PARK 2, #01-367, ANG MO KIO INDUSTRIAL PARK 2, SINGAPORE 569538			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	