



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 4206T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BENT / DENTED	855.90	855.90
1	FRONT BONNET LOGO	NECESSARY	65.80	65.80
1	FRONT BONNET LOCK	NOT NECESSARY	95.20	-
2	FRONT CORNER PANELS	NOT NECESSARY	753.00	-
2	FRONT HEADLAMPS	NOT NECESSARY	1,921.60	-
1	FRONT GRILLE	GRAZED	355.80	355.80
1	FRONT BUMPER BEAM	NOT NECESSARY	288.60	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	288.60	-
2	FRONT BUMPER SIDE RETAINERS	NOT NECESSARY	178.60	-
	LESS 25% DISCOUNT		-1,200.78	-319.38
			3,602.32	958.12
1	FRONT BUMPER (50%) (SN)	GRAZED	862.16	431.08
	LESS 25% DISCOUNT		-215.54	-
			646.62	431.08
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.	NOT NECESSARY	80.00	-
	TO APPLY UNDERCOATING.		100.00	30.00
	PANEL BEATING.		1,400.00	300.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS .		1,200.00	300.00
			2,780.00	630.00
	GRAND TOTAL		7,078.94	2,019.20



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	-----------------

Report Ref No. CS/FCI22011099/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.