

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011100/AVP3Q2**Date:** 20/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00002032200		
Claimant Vehicle No :	SDV1221J	Insured Vehicle No :	SND7658U		
Date of Loss:	03/11/2022	Nature of Claim:	TP	Claim No:	SNM22D207961/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDV1221J	Engine No:	27294630652729
Make & Model:	MERCEDES-BENZ S300L, 3.0 (A)	Chassis No:	WDD2211542A148233
Reg. Date:	19/12/2007 (Man. Year: 2007)	Odometer:	116848 km
Colour:	White		
Engine Capacity:	2997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R20	Rear Tyre Size:	255/35 R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,501.02	6,268.82	19,232.20	75.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	1,570.00	3,330.00	67.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,401.02	7,838.82	22,562.20	74.22
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	30,401.02	6,250.00	24,151.02	79.44
+ GST 8.00/8.00% (S\$)	2,432.08	500.00	1,932.08	79.44
Nett Amount (S\$)	32,833.10	6,750.00	26,083.10	79.44

INSPECTION

Date of Assignment:	10/11/2022	Autobacs Car Care (Singapore) Pte Ltd (HQ)
Date Inspected:	07/11/2022 Inspected At:	8 Kaki Bukit Ave 4,, #08-45/46 Premier@Kaki Bukit,
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2023)
Parts:	143	MERCEDES-BENZ S300L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDV1221J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,935.00 FL	*1,850.00 FL
2	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	72.00 FL	*- FL
3	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	265.00 FL	*- FL
4	1		*SET REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	150.00 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	75.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	810.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	75.00 FL	*- FL
8	1		*REAR END PANEL	Not Necessary	2,850.00 FL	*- FL
9	1		*REAR TAILLAMP RH	Not Necessary	810.00 FL	*- FL
10	1		*REAR TAILLAMP BRACKET RH	Not Necessary	85.00 FL	*- FL
11	1		*REAR TAILLAMP PANEL RH	Not Necessary	689.00 FL	*- FL
12	1		*REAR FENDER INNER TRIM	Not Necessary	895.00 FL	*- FL
13	1		*REAR FENDER COWLING	Not Necessary	284.00 FL	*- FL
14	1		*REAR FENDER INNER SHIELD RH	Not Necessary	286.80 FL	*- FL
15	1		*REAR FENDER INNER AIR VENT RH	Not Necessary	85.30 FL	*- FL
16	1		*REAR FENDER TOP GARNISH RH	Not Necessary	95.80 FL	*- FL
17	1		*REAR FENDER INNER UPHOLSTERY TRIM RH	Not Necessary	540.20 FL	*- FL
18	1		*REAR SHOCK ABSORBER	Not Necessary	842.20 FL	*- FL
19	1		*REAR WHEEL BEARING	Damaged	780.00 FL	*585.00 FL
20	1		*REAR SUSPENSION UPPER ARM RH	Bent	480.60 FL	*480.60 FL
21	1		*REAR SUSPENSION TRAILING ARM RH	Bent	356.60 FL	*356.60 FL
22	1		*REAR SUSPENSION KNUCKLE ARM RH	Damaged	1,014.50 FL	*950.00 FL
23	1		*REAR SUSPENSION KNUCKLE ARM BEARING RH	Not Necessary	746.50 FL	*- FL
24	1		*REAR SUSPENSION LOWER ARM	Bent	589.60 FL	*589.60 FL
25	1		*SIDE SKIRT RH	Not Necessary	780.40 FL	*- FL
26	1		*REAR DOOR	Not Necessary	2,426.30 FL	*- FL
27	1		*REAR AXLE RH	Not Necessary	5,800.00 FL	*- FL
28	1		*REAR SPORT RIM RH (ORIGINAL)	Cut	2,385.00 FS	*1,200.00 FS
29	1		*REAR AXEL MOUNTING	Damaged	398.00 FL	*398.00 FL
30	1		*REAR TYRE RH	Cut	580.00 FS	*300.00 FS
31	1		*REAR TAILLAMP CLIPS	Not Necessary	80.00 FS	*- FS
32	1		*REAR FENDER SEALANT RH	Not Necessary	120.00 FS	*- FS
33	1		*REAR FENDER INNER PANEL SEALANT RH	Not Necessary	100.00 FS	*- FS
34	1		*REAR WINDSCREEN SEALANT WITH PRIMER	Not Necessary	120.00 FS	*- FS
35	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
36	1		*REAR DOOR BOARD CLIPS	Not Necessary	60.00 FS	*- FS
37	1		*SET REAR BUMPER RIVET	Necessary	100.00 FS	*30.00 FS
38	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,922.80	6,789.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,421.78	520.98
Total Parts (\$\$)	25,501.02	6,268.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,800.00	500.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,400.00	500.00
3	TO APPLY ANTI-RUST & TUFF-KOTE	New	150.00	40.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
5	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	150.00	50.00
6	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	100.00	0.00
7	TO WHEEL ALIGNMENT	New	150.00	80.00
8	TO DISMANTLE & REPLACED REAR WINDSCREEN PERFORM	New	150.00	0.00
9	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	350.00	120.00
10	TO DISMANTLE REAR UNDERCARRIAGE	New	500.00	250.00
Gross Labour Cost (S\$)			4,900.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >