



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 4652D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED / DENTED	1,135.90	1,135.90
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	458.65	-
1	TAIL GATE	TO REPAIR SEE LABOUR	3,270.15	-
1	TAIL GATE LAMP	CUT	1,109.30	885.00
1	Q5 EMBLEM	NECESSARY	72.30	72.30
1	2 OF EMBLEM	NECESSARY	72.30	72.30
1	CENTRE EMBLEM	NECESSARY	93.65	93.65
	LESS 10% DISCOUNT		-621.23	-225.92
			5,591.02	2,033.23
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	40.00	-
			40.00	-
LABOUR				
	TO PUTTY & SPRAY PAINT.		600.00	440.00
	TO REMOVE & TRANSFER REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	TO TRANSFER TAIL GATE FITTING.	NOT NECESSARY	80.00	-
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND TAIL GATE.		450.00	400.00
			1,250.00	840.00
GRAND TOTAL			6,881.02	2,873.23
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS/FCI22011102/Kny3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.