

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22011107/AWY3Q2**Date:** 02/03/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLZ4433D **Insured Vehicle No :** SCR638E

Date of Loss: 05/11/2022 Nature of Claim: TP Claim No: CDMPG22002387

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ4433D**

Make & Model: HONDA FIT, 1.3 (A) Engine No: L13A4173067

Reg. Date: 25/06/2009 (Man. Year: 2009) Chassis No: GE61158331

Colour: Red Odometer: 168643 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,478.96	4,187.76	8,291.20	66.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,320.00	2,680.00	3,640.00	57.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,798.96	6,867.76	11,931.20	63.47
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	18,798.96	5,500.00	13,298.96	70.74

INSPECTION

Date of Assignment: 07/11/2022

Date Inspected: 08/11/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2023)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ4433D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR DOOR HINGE RH	Not Necessary	117.20 FL	*- FL
2	1		*REAR DOOR INNER LOCK RH	Not Necessary	342.20 FL	*- FL
3	1		*REAR DOOR LOCK CATCHER RH	Not Necessary	41.40 FL	*- FL
4	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	136.80 FL	*- FL
5	1		*REAR DOOR INNER TRIM RH	Not Necessary	784.40 FL	*- FL
6	1		*TAIL LAMP RH	Cracked	296.10 FL	*296.10 FL
7	1		*TAIL LAMP LOWER BRACKET RH	Damaged	17.20 FL	*17.20 FL
8	1		*TAIL LAMP PANEL RH (OUTER)	Dented	168.30 FL	*168.30 FL
9	1		*REAR FENDER RH	Distorted	677.80 FL	*677.80 FL
10	1		*REAR FENDER INNER COWLING RH	Torn	78.10 FL	*78.10 FL
11	1		*REAR FENDER INNER TRIM RH	Deformed	298.90 FL	*298.90 FL
12	1		*REAR FENDER INNER UPPER TRIM RH	Not Necessary	189.60 FL	*- FL
13	1		*REAR FENDER INNER PANEL RH	Buckled	764.20 FL	*764.20 FL
14	1		*REAR WHEEL HOUSE PANEL RH	Repair	997.70 FL	*- FL
15	1		*REAR WHEEL HOUSE UPPER PANEL RH	Repair	439.80 FL	*- FL
16	1		*REAR FENDER AIR VENT RH	Deformed	72.30 FL	*72.30 FL
17	1		*REAR QUARTER GLASS INNER PANEL RH	Not Necessary	455.70 FL	*- FL
18	1		*REAR QUARTER GLASS C/W MOULDING	Necessary	280.00 FL	*45.00 FL
19	1		*REAR ABS SENSOR RH	Not Necessary	249.70 FL	*- FL
20	1		*REAR AXLE	Not Necessary	1,595.40 FL	*- FL
21	1		*REAR SHOCK ABSORBER RH	Not Necessary	439.40 FL	*- FL
22	1		*REAR WHEEL HUP C/W BEARING RH	Damaged	375.30 FL	*225.00 FL
23	1		*REAR BUMPER	Distorted	490.00 FL	*490.00 FL
24	2		*REAR BUMPER BRACKET	Not Necessary	108.20 FL	*- FL
25	1		*REAR BUMPER SIDE RETAINER	O/S Damaged	70.40 FL	*35.20 FL
26	1		*REAR BUMPER TOWING COVER	Deformed	28.60 FL	*28.60 FL
27	1		*REAR END PANEL	Deformed	356.70 FL	*356.70 FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	116.20 FL	*116.20 FL
29	1		*REAR TOOLS BOX	Torn	294.00 FL	*294.00 FL
30	1		*CENTER EXHAUST	Not Necessary	769.30 FL	*- FL
31	1		*CENTER EXHAUST INSULATOR	Not Necessary	49.80 FL	*- FL
32	1		*SET CENTER EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
33	1		*REAR EXHAUST PIPE	Not Necessary	688.70 FL	*- FL
34	1		*REAR EXHAUST INSULATOR	Not Necessary	58.40 FL	*- FL
35	1		*SET REAR EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
36	4		*REAR EXHAUST MOUNTING	Not Necessary	84.80 FL	*- FL
37	1		*REAR FLOOR SIDE PANEL RH	Dented	196.10 FL	*196.10 FL
38	1		*SET REAR DOOR TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
39	1		*REAR FENDER GLASS SOLAR FILM RH	Not Necessary	250.00 FS	*- FS
40	1		*SET ROOF MOULDING CLIP RH	Not Necessary	30.00 FS	*- FS
41	1		*SET REAR DOOR STEP INNER GARNISH CLIP RH	Not Necessary	50.00 FS	*- FS
42	1		*REAR WHEEL HOUSE PANEL SEALANT	Not Necessary	120.00 FS	*- FS
43	1		*REAR FENDER SEALANT RH	Necessary	80.00 FS	*40.00 FS
44	1		*SET REAR FENDER COWLING CLIP	Necessary	50.00 FS	*30.00 FS
45	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
46	1		*REAR FENDER QUARTER GLASS SEALANT RH	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

3/2/23, 11:01 PM			Adjuster Report			
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FENDER QUARTER GLASS INNER SHIELD RH	Not Necessary	60.00 FS	*- FS
48	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
49	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
50	1		*REAR WHEEL SPORT RIM RH	Cut	850.00 FS	*450.00 FS
51	1		*REAR WHEEL SPORT TYRE RH	Not Necessary	450.00 FS	*- FS
52	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
53	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS
54	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	14,928.70
					- List Item Discount on L Items 20.00/20.00% (\$)	2,449.74
					Total Parts (\$)	12,478.96
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	1,200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	100.00
4	WIRING BULB CHECKING	New	180.00	30.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
6	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
7	TRANFER REAR DOOR MECHANISM	New	80.00	0.00
8	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	100.00
9	TO PRESS REAR WHEEL HUB BEARING	New	80.00	0.00
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
11	FOUR WHEEL ALIGNMENT	New	120.00	80.00
12	REMOVE AND REFIX REAR FENDER GLASS	New	100.00	40.00
13	RESET ABS LIGHT	New	350.00	0.00
14	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			6,320.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >