

Vehicle Damage Assessment Report for [SLZ4433D]

Estimate Created: 24/02/2023 14:07 by Insurlogic 5 (Insurlogic_Pte_Ltd)

Owned: 24/02/2023 14:22 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Fit
Engine Type			
License Plate Number	SLZ4433D	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$5,500 WITH 8 DAYS

Insurlogic 5 (24/02/2023 14:21)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
TAILLAMP RH		1	296.10	-20.00 %	236.88
TAILLAMP BRACKET RH		1	17.20	-20.00 %	13.76
TAILLAMP PANEL RH (OUTER)		1	168.30	-20.00 %	134.64
REAR FENDER RH		1	677.80	-20.00 %	542.24
REAR FENDER INNER COWLING RH		1	78.10	-20.00 %	62.48
REAR FENDER INNER TRIM RH		1	298.90	-20.00 %	239.12
REAR FENDER INNER PANEL RH		1	764.20	-20.00 %	611.36
REAR FENDER AIR VENT RH		1	72.30	-20.00 %	57.84
REAR QTR GLASS C/W MOULDING		1	95.00	-20.00 %	76.00
REAR WHEEL HUB C/W BEARING RH		1	225.00	-20.00 %	180.00
REAR BUMPER		1	490.00	-20.00 %	392.00
REAR BUMPER SIDE RETAINER RH		1	35.20	-20.00 %	28.16
REAR BUMPER TOW COVER		1	28.60	-20.00 %	22.88
REAR END PANEL		1	356.70	-20.00 %	285.36
REAR END PANEL TOP GARNISH		1	116.20	-20.00 %	92.96
REAR TOOLS BOX		1	294.00	-20.00 %	235.20
REAR FLOOR SIDE PANRL RH		1	196.10	-20.00 %	156.88

Parts Subtotal 3,367.76

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR FENDER SEALANT RH		1.0	40.00	0.00 %	40.00
REAR FENDER COWLING CLIP SET		1.0	30.00	0.00 %	30.00
REAR FENDER INNER TRIM CLIP SET		1.0	30.00	0.00 %	30.00
REAR FENDER QTR GLASS SEALANT		1.0	40.00	0.00 %	40.00
REAR END PANEL INSULATION SEAL		1.0	60.00	0.00 %	60.00

REAR END PANEL TOP GARNISH CLIP SET	1.0	10.00	0.00 %	10.00
REAR WHEEL SPORT RIM RH	1.0	450.00	0.00 %	450.00
REVERSE SENSOR	1.0	200.00	0.00 %	200.00

Materials Subtotal 860.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING, REMOVING & REPLACING PARTS	RnR	1200.00	0.00 %	1,200.00
TUFF COAT	RnR	100.00	0.00 %	100.00
WIRING & BULB CHECKING	RnR	30.00	0.00 %	30.00
REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	RnR	80.00	0.00 %	80.00
REMOVE & REFIX REAR UNDERCARRIAGE	RnR	100.00	0.00 %	100.00
4 WHEEL ALIGNMENT	RnR	80.00	0.00 %	80.00
REMOVE & REFIX REAR FENDER GLASS	RnR	40.00	0.00 %	40.00
REMOVE & REFIX REVERSE SENSOR & DIAGNOSE SETTING	RnR	50.00	0.00 %	50.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING TO AFFECTED AREA	Full spray	1000.00	0.00 %	1,000.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,680.00

Paint Labor Subtotal 1,000.00

Labor Subtotal 2,680.00

Summary

Repair Cost	6,907.76
Discount(20 %)	(1,379.55)
	5,528.21
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,528.21