

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011111/PA3Q2**Date:** 11/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900021527
Claimant Vehicle No :	GBC1543D	Insured Vehicle No :	SJP9651J
Date of Loss:	03/11/2022	Nature of Claim:	TP
		Claim No:	3856686819SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC1543D	Engine No:	198A30006629398
Make & Model:	FIAT DOBLO, 1.6 D CARGO MJ (M)	Chassis No:	ZFA26300009098343
Reg. Date:	13/06/2011 (Man. Year: 2011)	Odometer:	288564 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Lassa 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Lassa 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,905.00	877.50	3,027.50	77.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	1,170.00	520.00	30.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,595.00	2,047.50	3,547.50	63.40
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	5,595.00	1,600.00	3,995.00	71.40
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,842.00		

INSPECTION

Date of Assignment:	08/11/2022	
Date Inspected:	08/11/2022 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Cut	745.00 F	*745.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
3	1		*REAR TAIL LAMP RH	Not Necessary	520.00 F	*- FL
4	1		*REAR FENDER RH (BODY PANEL)	Repair	2,350.00 F	*- FL
5	1		*REAR WHEEL HUB -CAB	Cut	225.00 F	*180.00 FL
					Sub Total (\$)	3,905.00 975.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00 97.50
					Total Parts (\$)	3,905.00 877.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	40.00	20.00
2	LABOR FOR PANEL BEATING ,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	550.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	800.00	600.00
4	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	0.00
Gross Labour Cost (\$\$)			1,690.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >