

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011116/KPA3Q2**Date:** 10/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100190170
Claimant Vehicle No :	SMZ3778D	Insured Vehicle No :	SJV5095J
Date of Loss:	25/10/2022	Nature of Claim:	TP
		Claim No:	7467008152SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ3778D	Engine No:	L15B5571205
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11321167
Reg. Date:	23/04/2021 (Man. Year: 2019)	Odometer:	120700 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Arivo 9 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Arivo 9 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,777.80	1,848.48	1,929.32	51.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	785.00	1,055.00	57.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,617.80	2,633.48	2,984.32	53.12
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	5,617.80	2,100.00	3,517.80	62.62
+ GST 7.00/7.00% (S\$)	393.25	147.00	246.25	62.62
Nett Amount (S\$)	6,011.05	2,247.00	3,764.05	62.62
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,575.45		

INSPECTION

Date of Assignment:	04/11/2022	
Date Inspected:	04/11/2022	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,210.90 FL	*953.30 FL
2	1		*REAR TAILGATE VEZEL EMBLE	Necessary	55.10 FL	*55.10 FL
3	1		*REAR TAILGATE HONDA LOGO	Necessary	58.50 FL	*58.50 FL
4	1		*SET REAR TAILGATE WINDSCREEN MOULDING	Necessary	181.00 FL	*181.00 FL
5	1		*REAR TAILGATE INNER LOCK	Repair	198.40 FL	*- FL
6	1		*REAR TAILGATE INNER RUBBER	Serviceable	135.20 FL	*- FL
7	1		*REAR TAILGATE INNER GARNISH	Serviceable	420.50 FL	*- FL
8	1		*REAR BUMPER	Buckled	986.30 FL	*762.70 FL
9	1		*REAR END PANEL	Repair	580.90 FL	*- FL
10	1		*REAR END PANEL INNER GARNISH	Serviceable	250.20 FL	*- FL
11	1		*REAR END PANEL OUTER SENSOR	Serviceable	195.25 FL	*- FL
12	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
13	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,632.25	2,250.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	854.45	402.12
Total Parts (\$\$)	3,777.80	1,848.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	60.00	15.00
3	TUFFKOTE	New	60.00	30.00
4	SPRAY PAINTING	New	800.00	220.00
5	LABOUR CHARGES	New	800.00	400.00
Gross Labour Cost (S\$)			1,840.00	785.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >