

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG22011118/EQCE2**Date:** 04/01/2023**REFERENCE**

Insured/Claimant:	CHAUDHARI AJAY ASHOK	Policy No:	7210004265	
Date of Loss:	31/10/2022	Nature of Claim:	OD	Claim No: 9505114196SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX8267P	Engine No:	DEM025744
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF53MA004285
Reg. Date:	30/01/2021 (Man. Year: 2020)	Odometer:	39321 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$190,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,275.00	5,081.76	28,193.24	84.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,272.00	2,972.00	4,300.00	59.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,547.00	8,053.76	32,493.24	80.14
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	38,947.00	6,453.76	32,493.24	83.43
+ GST 7.00/7.00% (S\$)	2,726.29	451.76	2,274.53	83.43
Nett Amount (S\$)	41,673.29	6,905.52	34,767.77	83.43

INSPECTION

Date of Assignment:	07/11/2022	
Date Inspected:	07/11/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,493.00 FS	*- FS
2	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*- FS
5	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	144.00 FS	*- FS
6	1		*FRONT BUMPER END PLATE	Broken	293.00 FS	*234.00 FS
7	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	302.00 FS	*- FS
8	2		*FRONT BUMPER OUTER GRILLE HOLE COVER - LH / RH	Not Necessary	108.00 FS	*- FS
9	1		*RADIATOR GRILLE TRIM - CENTER	Not Necessary	127.00 FS	*- FS
10	1		*RADIATOR GRILLE	Broken	1,881.00 FS	*1,504.80 FS
11	1		*RADIATOR GRILLE COVER CAP	Missing	141.00 FS	*112.40 FS
12	1		*RADIATOR GRILLE BRACKET	Not Necessary	19.00 FS	*- FS
13	1		*FRONT 360 CAMERA	Not Necessary	1,264.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	163.00 FS	*- FS
16	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	82.00 FS	*- FS
17	1		*FRONT BUMPER TOP COVER	Broken	143.00 FS	*114.00 FS
18	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
19	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
20	1		*LOCK CARRIER BRACKET	Broken	154.00 FS	*122.80 FS
21	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
22	1		*HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
23	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
24	2		*HORN BRACKET - LH / RH	Not Necessary	66.00 FS	*- FS
25	2		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	531.00 FS	*- FS
26	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	531.00 FS	*- FS
27	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
28	1		*BONNET	Dented	3,491.00 FS	*2,792.80 FS
29	2		*BONNET HINGE - LH / RH	Not Necessary	932.00 FS	*- FS
30	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
31	2		*FRONT FENDER LEDGE COVER - LH / RH INNER	Not Necessary	98.00 FS	*- FS
32	2		*BONNET STRIKER - LH / RH	Not Necessary	112.00 FS	*- FS
33	2		*BONNET LOCK - LH / RH	Not Necessary	455.00 FS	*- FS
34	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
35	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
36	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
37	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
38	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
39	2		*HEADLIGHT - LH / RH	Not Necessary	16,344.00 FS	*- FS
40	2		*LIFT CYLINDER - LH / RH	Not Necessary	434.00 FS	*- FS
41	2		*LIFT CYLINDER BRACKET - LH / RH	Not Necessary	34.00 FS	*- FS
42	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
43	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
44	2		*RADIATOR AIR GUIDE - LH / RH INNER	Not Necessary	72.00 FS	*- FS
45	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Not Necessary	38.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
47	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
48	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
49	1		*SUNDRIES	Necessary	400.00 FS	*48.72 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 33,275.00 5,081.76

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEDLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	580.00	580.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	900.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,500.00	1,000.00
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (S\$)			7,272.00	2,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >