



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 564Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	SEAL, HOOD TO FR END (SN)	NOT NECESSARY	55.80	-
1	SUPPORT, FR BUMPER (SN)	BROKEN	95.70	95.70
1	COVER, FR BUMPER (SN)	BROKEN	560.30	560.30
1	FENDER SUB-ASSY, FR (SN)	DENTED	1,060.70	1,060.70
1	LINER, FR FENDER, RH (SN)	CRUSHED	223.50	223.50
1	EMBLEM SUB-ASSY, (SN)	NECESSARY	77.40	77.40
1	UNIT, HEADLAMP (SN)	NOT NECESSARY	2,852.40	-
			5,025.80	2,067.60
LABOUR				
CHECK WIRING AND REFOCUS HEADLAMP.			198.00	198.00
REPL ACC AFF PARTS AND PANEL.			2,376.00	1,584.00
RESPRAY ACC AFF AREA.			2,624.00	1,312.00
TO RESET ECU AND REPROGRAMME.			198.00	198.00
CONDUCT WHEEL ALIGNMENT.			198.00	198.00
			5,594.00	3,490.00
GRAND TOTAL			10,619.80	5,557.60
RECOMMENDED COST OF REPAIRS				5,557.60

Report Ref No. CS/FCI22011131/Ewy3m4

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.