

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22011134/TNY3Q2**Date:** 28/12/2022**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU006660		
Claimant Vehicle No :	SHC8651H	Insured Vehicle No :	SLP5423D		
Date of Loss:	06/11/2022	Nature of Claim:	TP	Claim No:	M2206246

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8651H	Engine No:	D4FDEU480298
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU085760
Reg. Date:	17/03/2016 (Man. Year: 2015)	Odometer:	888541 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,154.98	828.10	326.88	28.30
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	810.00	560.00	250.00	30.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,975.98	1,399.10	576.88	29.19
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	1,975.98	1,100.00	875.98	44.33
+ GST 7.00/7.00% (S\$)	138.32	77.00	61.32	44.33
Nett Amount (S\$)	2,114.30	1,177.00	937.30	44.33

INSPECTION

Date of Assignment:	07/11/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	08/11/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8651H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
2	1		*REAR BUMPER LOWER COVER	Deformed	228.00 FL	*228.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	*- FL
4	1		*REAR BUMPER CLIPS	Necessary	2.20 FL	*22.00 FL
5	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
6	1		*REAR BUMPER REVERSE SENSOR	Necessary	135.70 FS	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,397.30	988.70
- List Item Discount on L Items 20.00/20.00% (S\$)	242.32	160.60
Total Parts (S\$)	1,154.98	828.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	450.00	280.00
2	SPRAY PAINTING	New	300.00	250.00
3	REMOVE/ REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (\$\$)			810.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >