

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22011136/RQY3E2**Date:** 05/07/2023REFERENCE

Insured/Claimant: SHARON DOMINIQUE KHONG SWEE AI

Policy No: MPC22P00110300

Date of Loss: 03/11/2022

Nature of Claim: OD

Claim No: DMPC2200539H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMT7737C**

Make & Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)

Engine No: K24W72011955

Reg. Date: 23/05/2016 (Man. Year: 2016)

Chassis No: JHMRC1890GC204187

Colour: White

Odometer: 174618 km

Engine Capacity: 2356 cc

Market Value/New Car Price: S\$85,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,491.00	3,320.00	1,171.00	26.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,320.00	420.00	24.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,231.00	4,640.00	1,591.00	25.53
+ GST 7.00/8.00% (S\$)	436.17	371.20	64.97	14.90
Nett Amount (S\$)	6,667.17	5,011.20	1,655.97	24.84

INSPECTION

Date of Assignment: 08/11/2022 Present Location:

Vin's Motor Pte Ltd (Sin Ming)

Date Inspected: 08/11/2022 Inspected At:

Vin's Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive, #03-03, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2023)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT7737C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (WCP)	Bent	820.00 F	*820.00 F
2	1		*TAILGATE GLASS RH MOULDING (WCP)	Necessary	30.00 F	*30.00 F
3	1		*TAILGATE GLASS LH MOULDING (WCP)	Necessary	30.00 F	*30.00 F
4	2		*TAILGATE GLASS TOP MOULDING (WCP)	Necessary	60.00 F	*60.00 F
5	2		*TAILGATE GLASS SIDE MOULDING (WCP)	Necessary	80.00 F	*80.00 F
6	1		*TAILGATE EMBLEM (WCP)	Necessary	40.00 F	*40.00 F
7	1		*TAILGATE CENTRE REFLECTOR (WCP)	Cut	160.00 F	*160.00 F
8	1		*TAILGATE RH REFLECTOR (WCP)	Cracked	280.00 F	*280.00 F
9	1		*TAILGATE LH REFLECTOR (WCP)	Cracked	280.00 F	*280.00 F
10	1		*TAILGATE LOWER CHROME MOULDING (WCP)	Cracked	110.00 F	*150.00 F
11	1		*TAILGATE INNER TRIMBOARD (WCP)	Cracked	180.00 F	*180.00 F
12	1		*TAILGATE REVERSE CAMERA (WCP)	Not Necessary	420.00 F	*- F
13	1		*TAILGATE INNER LOCK (WCP)	Cut	110.00 F	*110.00 F
14	1		*TAILGATE RUBBER (WCP)	Necessary	80.00 F	*80.00 F
15	1		*REAR BUMPER (WCP)	Deformed	480.00 F	*480.00 F
16	2		*REAR BUMPER PARKING SENSOR	Cut	440.00 F	*200.00 FS
17	1		*REAR BUMPER RH SIDE RETAINER (WCP)	Not Necessary	20.00 F	*- F
18	1		*REAR BUMPER LH SIDE RETAINER (WCP)	Not Necessary	20.00 F	*- F
19	10		*REAR BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
20	1		*REAR END PANEL (WCP)	Repair	350.00 F	*- F
21	1		*WINDSCREEN GUM	Necessary	80.00 FS	*40.00 FS
						F=Franchise part. S=SpcNett.
					Sub Total (\$\$)	4,090.00 3,040.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	401.00 280.00
					Total Parts (\$\$)	4,491.00 3,320.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX TAILGATE GLASS	New	180.00	120.00
2	TO REPAIR DAMAGES	New	680.00	500.00
3	TO SPRAY PAINTING (PEARL)	New	880.00	700.00
Gross Labour Cost (\$)			1,740.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >