

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS22011138/TWY3M4**Date:** 10/01/2023**REFERENCE**

Insured/Claimant:	BOEY JIA RONG	Policy No:	SP2001950571-01	
Date of Loss:	04/11/2022	Nature of Claim:	OD	Claim No: 202222007941/JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ6363G		
Make & Model:	BMW 216I, 1.5 GRAN TOURER NAV (A)	Engine No:	37035490B38A15A
Reg. Date:	26/12/2018 (Man. Year: 2018)	Chassis No:	WBA6V120X0ED05698
Colour:	Bronze	Odometer:	69753 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R17	Rear Tyre Size:	205/55R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,573.86	8,166.46	7,407.40	47.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,170.00	2,580.00	68.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,323.86	9,336.46	9,987.40	51.68
Approved Total (Overridden) (\$\$)		7,450.00		
- Excess (\$\$)	600.00	600.00	0.00	0.00
Nett Amount (\$\$)	18,723.86	6,850.00	11,873.86	63.42

INSPECTION

Date of Assignment: 07/11/2022

Date Inspected: 10/11/2022 Inspected At:

Estimated Period of Repair: 4.0 days

TEAM AUTOCARE PTE LTD
160 SIN MING DRIVE,
#02-12, SIN MING AUTOCITY, SINGAPORE
575722

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts:	M1-MPV	BMW 216I 1.5 GRAN TOURER NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ6363G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Repair	1,110.35 F	*- F
2	2		*BONNET INNER LOCK (WCP)	Not Necessary	377.30 F	*- F
3	1		*FRONT BUMPER (WCP)	Deformed	1,009.75 F	*1,009.75 F
4	1		*FRONT BUMPER LOGO (WCP)	Necessary	88.00 F	*88.00 F
5	2		*FRONT BUMPER SIDE RETAINER (WCP)	Not Necessary	570.80 F	*- F
6	1		*FRONT BUMPER SIDE CARRIER (WCP)	Broken	378.22 F	*378.22 F
7	1		*FRONT BUMPER INNER SPONGE (WCP)	Broken	249.70 F	*249.70 F
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	681.40 F	*- F
9	1		*FRONT BUMPER LOWER GRILLE (WCP)	Broken	482.60 F	*482.60 F
10	2		*FRONT BUMPER LOWER SIDE GRILLE (WCP)	Not Necessary	778.00 F	*- F
11	2		*FRONT BUMPER LOWER SIDE GRILLE CHROME (WCP)	Distorted	294.60 F	*294.60 F
12	1		*FRONT BUMPER PARKING SENSOR (4PCS) (WCP)	Shorted (2Pcs Only)	840.00 F	*410.00 F
13	2		*FRONT GRILLE (WCP)	Broken	947.20 F	*947.20 F
14	2		*FRONT GRILLE OUTER CHROME (WCP)	Cut	516.00 F	*516.00 F
15	1		*HEADLAMP RH (WCP)	Cracked	2,595.75 F	*2,595.75 F
16	1		*HEADLAMP LOWER BRACKET RH (WCP)	Broken	238.60 F	*238.60 F
17	1		*FRONT SUPPORT PANEL (WCP)	Not Necessary	1,843.60 F	*- F
18	1		*FRONT SUPPORT PANEL TOP GARNISH (WCP)	Not Necessary	418.00 F	*- F
19	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
20	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
21	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
22	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	60.00 FS	*- FS
23	2		*FRONT BUMPER LOWER SIDE GRILLE CLIPS	Not Necessary	120.00 FS	*- FS
24	4		*FRONT BUMPER PARKING SENSOR SEAL	Necessary	192.00 FS	*120.00 FS
25	2		*FRONT GRILLE CLIPS	Necessary	120.00 FS	*40.00 FS
26	1		*FRONT NUMBER PLATE W/CASING	Bent	80.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)		14,231.87	7,445.42
+ Margin on L,N Items 10.00/10.00% (S\$)		1,341.99	721.04
Total Parts (S\$)		15,573.86	8,166.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT BUMPER PARKING SENSOR	New	150.00	40.00
2	R&R RADIATOR	New	150.00	0.00
3	R&R A/C CONDENSER	New	150.00	0.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	150.00
5	FRONT CHECK WIRING	New	100.00	50.00
6	FRONT UPHOLSTERY	New	200.00	0.00
7	FRONT PANEL BEATING	New	1,200.00	400.00
8	FRONT RUST PROOFING	New	300.00	30.00
9	FRONT SPRAY PAINTING	New	1,200.00	500.00
Gross Labour Cost (\$\$)			3,750.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >