



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 2170Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR ALUMINIUM TAILGATE (SN)	CRACKED	4,000.00	3,000.00
1	REAR TAILGATE CARRIER (SN)	BENT	3,500.00	2,000.00
2	REAR CENTRE HYDRAULIC @\$4000.00 (SN) (BENT)	NOT CONSISTENT WITH THE IMPACT	8,000.00	-
2	REAR SIDE HYDRAULIC @\$3000.00 (SN)	BENT	6,000.00	4,000.00
1	SET REAR CARRIER SAFETY STICKER (SN)	NECESSARY	120.00	100.00
2	REAR TAILGATE SAFETY STICKER (SN)	NECESSARY	160.00	120.00
1	60KM/HR STICKER (SN)	NECESSARY	30.00	30.00
1	HYDRAULIC OIL (SN) (50%)	NECESSARY	250.00	100.00
			22,060.00	9,350.00
<u>LABOUR</u>				
	CHECK WIRING.		100.00	20.00
	LABOUR TO REMOVE & REFIT REAR TAILGATE.		300.00	250.00
	LABOUR TO REMOVE & REFIT TAILGATE CARRIER.		500.00	200.00
	LABOUR TO REMOVE & REFIT REAR HYDRAULIC AND SERVICE.		500.00	400.00
	SPRAY PAINTING.		1,000.00	400.00
			2,400.00	1,270.00
GRAND TOTAL			24,460.00	10,620.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,500.00

Report Ref No. CS3/LPC22007491/Kvy3e2-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.