

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011150/EPA3Q2**Date:** 19/05/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000545
Claimant Vehicle No : SFW8998B **Insured Vehicle No :** SNB3785Y
 Date of Loss: 06/11/2022 Nature of Claim: TP Claim No: AWLAISCL2022-009

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFW8998B**
 Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CXS095942
 Reg. Date: 28/06/2014 (Man. Year: 2014) Chassis No: WAUZZZ8V2E1037387
 Colour: Grey Odometer: 90601 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
 Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,062.00	10,536.50	13,525.50	56.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,144.00	9,094.00	3,050.00	25.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,206.00	19,630.50	16,575.50	45.78
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	36,206.00	16,000.00	20,206.00	55.81
+ GST 8.00/8.00% (S\$)	2,896.48	1,280.00	1,616.48	55.81
Nett Amount (S\$)	39,102.48	17,280.00	21,822.48	55.81
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		18,287.45		

INSPECTION

Date of Assignment: 08/11/2022
 Date Inspected: 09/11/2022 Inspected At: Premium Automobiles Pte Ltd (HQ)
 55 UBI ROAD 1
 Singapore 408699
 Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2023)
Parts:	144	AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFW8998B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,377.00 FS	*2,377.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER STRIP MOLDING -LH	Not Necessary	182.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	175.00 FS	*- FS
5	4		*FRONT BUMPER PULL STRAP -LOWER	Not Necessary	231.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION -LH	Bent	43.00 FS	*42.80 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Missing	122.00 FS	*121.50 FS
8	1		*RADIATOR GRILLE	Not Necessary	765.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER	Not Necessary	109.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	154.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	63.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
15	1		*HORN LOW TONE-LH	Not Necessary	213.00 FS	*- FS
16	1		*FRONT FENDER -LH	Dented	954.00 FS	*954.00 FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
18	1		*FRONT FENDER BRACKET	Not Necessary	46.00 FS	*- FS
19	6		*FRONT FENDER RIVET	Necessary	23.00 FS	*22.80 FS
20	1		*FRONT FENDER BRACE	Bent	107.00 FS	*107.00 FS
21	1		*FRONT FENDER BRACKET -LH	Not Necessary	31.00 FS	*- FS
22	1		*FRONT FENDER CLOSING ELEMENT -LH	Not Necessary	37.00 FS	*- FS
23	1		*FRONT FENDER INSULATION -LH	Not Necessary	48.00 FS	*- FS
24	1		*FRONT WHEEL HOUSING LINER -LH	Broken	183.00 FS	*183.00 FS
25	1		*HEADLIGHT -LH	Broken	2,810.00 FS	*2,810.00 FS
26	1		*HEADLIGHT POWER MODULE	Not Necessary	635.00 FS	*- FS
27	1		*HEADLIGHT GAS DISCHARGE	Not Necessary	454.00 FS	*- FS
28	1		*HEADLIGHT GAS DISCHARGE CONTROL UNIT	Not Necessary	1,279.00 FS	*- FS
29	1		*HEADLIGHT HOSE-LH	Not Necessary	60.00 FS	*- FS
30	1		*LIFT CYLINDER -LH	Not Necessary	211.00 FS	*- FS
31	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
32	1		*LIFT CYLINDER PUMP	Not Necessary	172.00 FS	*- FS
33	1		*LIFT CYLINDER WASH WATER RESERVOIR	Deformed	226.00 FS	*225.50 FS
34	1		*LIFT CYLINDER WINDSCREEN WASHER SYSTEM PUMP	Not Necessary	138.00 FS	*- FS
35	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
36	1		*RADIATOR AIR GUIDE -LH	Not Necessary	28.00 FS	*- FS
37	1		*RADIATOR AIR GUIDE -UPPER CENTRE	Not Necessary	14.00 FS	*- FS
38	1		*FRONT DOOR -LH	Not Necessary	3,265.00 FS	*- FS
39	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	252.00 FS	*- FS
40	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
41	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
42	1		*FRONT DOOR CATCH -LH	Not Necessary	116.00 FS	*- FS
43	1		*FRONT EXTERIOR WING MIRROR MOUNTING -LH	Not Necessary	1,130.00 FS	*- FS
44	1		*FRONT WING MIRROR CAP -LH	Repair	180.00 FS	*- FS
45	1		*FRONT WING MIRROR GLASS -LH	Not Necessary	239.00 FS	*- FS
46	1		*FRONT WINDOW SLOT SEAL TRIM STRIP -LH	Not Necessary	346.00 FS	*- FS

Report was unsubmitted during this print-out.

5/19/23, 1:27 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT WINDOW GUIDE TRIM STRIP -LH	Not Necessary	287.00 FS	*- FS
48	1		*NOISE INSULATION	Not Necessary	377.00 FS	*- FS
49	1		*FRONT ALUMINIUM RIM -LH	Cut	1,303.00 FS	*1,303.00 FS
50	1		*CONTROL ARM -LH LOWER	Bent	394.00 FS	*393.50 FS
51	1		*FRONT WHEEL BEARING HOUSING	Bent	628.00 FS	*628.00 FS
52	1		*FRONT WHEELHUB BEARING	Necessary	554.00 FS	*554.00 FS
53	1		*CONTROL ARM GUIDE JOINT LH	Bent	137.00 FS	*137.00 FS
54	1		*COUPLING ROD	Not Necessary	105.00 FS	*- FS
55	1		*GAS SHOCK ABSORBER	Bent	282.00 FS	*282.00 FS
56	1		*TRACK ROD	Bent	99.00 FS	*98.20 FS
57	1		*TIE ROD END -LH	Bent	126.00 FS	*125.50 FS
58	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
59	1		*LHS FRONT TYRE (NPA)	Not Necessary	0.00 FS	*- FS
60	1		*SUNDRIES	Necessary	800.00 FS	*171.70 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					24,062.00	10,536.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	350.00
3	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES .INSPECT FOR DAMAGES	New	350.00	350.00
4	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER ,LHS FRONT DOOR AND LHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,800.00	2,100.00
5	TO RESPRAY FRONT BUMPER ,LHS FRONT FENDER ,LHS FRONT DOOR ,LHS WING MIRROR COVER ,LHS SILL PANEL AND LHS UPPER A-PILLAR	New	4,700.00	2,350.00
6	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY	New	2,400.00	2,400.00
7	TO RENEW LHS FRONT RIM WITH TYRE ,TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
9	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	280.00
Gross Labour Cost (S\$)			12,144.00	9,094.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >