



# 簡福星摩多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INDIA INTERNATIONAL INSURANCE PTE LTD  
64 CECIL STREET  
#04-05 IOB BUILDING  
SINGAPORE 049711

DATE : 08-11-2022

VEHICLE NO. : SMT1891D  
ACCIDENT DATE : 02-11-2022 20:00  
THIRD PARTY REF. : SHA2050S

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SMT1891D KIA CERATO 1.6(A) LX

| #  | QTY | PARTS DESCRIPTION                     | AMOUNT (SG\$)                   |
|----|-----|---------------------------------------|---------------------------------|
| 1  | 1   | FRONT BONNET                          | 580.00 <i>bt</i>                |
| 2  | 1   | FRONT BONNET LOCK                     | 43.00 <i>bt</i>                 |
| 3  | 2   | FRONT BONNET HINGES@\$22.00           | 44.00 <i>bt</i>                 |
| 4  | 1   | FRONT BONNET CABLE                    | 26.00 ?                         |
| 5  | 1   | FRONT SUPPORT PANEL                   | 280.00 <i>any</i>               |
| 6  | 1   | FRONT SUPPORT TOP GARNISH             | 65.00 <i>any</i>                |
| 7  | 8   | FRONT SUPPORT TOP GARNISH CLIP@\$2.50 | 20.00 <i>nes</i>                |
| 8  | 1   | FRONT GRILLE                          | 110.00 <i>any</i>               |
| 9  | 1   | FRONT EMBLEM                          | 23.00 <i>ant</i>                |
| 10 | 2   | FRONT HEADLAMP@\$390.00               | <i>RH?</i> 780.00 <i>LH any</i> |
| 11 | 2   | FRONT HEADLAMP LOWER BRACKET@\$18.00  | 36.00 ?                         |
| 12 | 2   | FRONT FENDER@\$165.00                 | 330.00 <i>Ry</i>                |
| 13 | 2   | FRONT FENDER SHIELD @\$58.00          | 116.00 <i>x</i>                 |
| 14 | 20  | FRONT FENDER SHIELD CLIP@\$2.50       | 50.00 <i>x</i>                  |
| 15 | 1   | FRONT BUMPER                          | 270.00 <i>de</i>                |
| 16 | 1   | FRONT BUMPER FOAM                     | 48.00 <i>de</i>                 |
| 17 | 1   | FRONT BUMPER REINFORCEMENT            | 200.00 <i>ht</i>                |
| 18 | 2   | FRONT BUMPER SIDE RETAINER@\$20.00    | 40.00 <i>nes</i>                |
| 19 | 1   | FRONT BUMPER LOWER GRILLE             | 150.00 <i>de</i>                |
| 20 | 2   | FRONT BUMPER FOGLAMP@\$115.00         | 230.00 <i>x</i>                 |
| 21 | 1   | FRONT BUMPER TOP BEAM                 | 110.00 ?                        |
| 22 | 1   | FRONT BUMPER FOGLAMP COVER LH         | 50.00 <i>ant</i>                |
| 23 | 1   | FRONT BUMPER LAMP LH                  | 95.00 ?                         |



# 簡福星摩多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : SMT1891D  
ACCIDENT DATE : 02-11-2022 20:00  
THIRD PARTY REF. : SHA2050S

| #  | QTY | PARTS DESCRIPTION            | AMOUNT (SG\$)    |
|----|-----|------------------------------|------------------|
| 24 | 10  | FRONT BUMPER CLIP@\$2.50     | 25.00 <i>AM</i>  |
| 25 | 1   | RADIATOR                     | 320.00 ?         |
| 26 | 1   | RADIATOR TOP HOSE            | 28.00 X          |
| 27 | 1   | RADIATOR LOWER HOSE          | 32.00 ?          |
| 28 | 1   | RADIATOR FAN ASSY            | 155.00 <i>CH</i> |
| 29 | 1   | SPARE TANK                   | 28.00 <i>de</i>  |
| 30 | 1   | WASHER TANK                  | 40.00 X          |
| 31 | 1   | WASHER TANK MOTOR            | 38.00 X          |
| 32 | 1   | AIR CON CONDENSER            | 320.00 <i>bt</i> |
| 33 | 2   | AIR CON SIDE GARNISH@\$20.00 | 40.00 ?          |
| 34 | 1   | AIR CON LIQUID PIPE          | 115.00 ?         |
| 35 | 1   | AIR CON SUCTION HOSE         | 115.00 ?         |
| 36 | 1   | AIR CON DISCHARGE HOSE       | 125.00 ?         |
| 37 | 1   | AIR DUCT                     | 65.00 <i>de</i>  |
| 38 | 1   | AIR CLEANER BOX ASSY         | 115.00 ?         |
| 39 | 1   | RESONATOR BOX                | 115.00 ?         |
| 40 | 1   | RESONATOR HOSE               | 65.00 ?          |
| 41 | 1   | MANIFOLD INTAKE              | 480.00 ?         |

5,917.00

ADD 20 %

1,183.40

TOTAL ( A )

7,100.40

### SPECIAL NETT ITEMS

1 1 FRONT NUMBER PLATE

TOTAL ( C )

*bt* 40.00

40.00

### LABOUR CHARGES

1 1 TO CHECK WIRING SYSTEM

30

50.00



# 簡福星噴砂工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : SMT1891D  
ACCIDENT DATE : 02-11-2022 20:00  
THIRD PARTY REF. : SHA2050S

| #              | QTY | PARTS DESCRIPTION                                                                | AMOUNT (SG\$) |
|----------------|-----|----------------------------------------------------------------------------------|---------------|
| 2              | 1   | TO REMOVE/REFIT/REFILL AIR CON GAS                                               | 100.00 ✓      |
| 3              | 1   | TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS | 750.00 600    |
| 4              | 1   | SPRAYPAINTING CHARGES                                                            | 700<br>820.00 |
| TOTAL ( D )    |     |                                                                                  | 1,720.00      |
| ESTIMATE TOTAL |     |                                                                                  | 8,860.40      |

Tanpin 97495949/62563561  
Not Advise 8/11/22 340pm  
Ex: to be advise  
6 days  
tanpin e lkhantowin  
p/p, Resurvey before paint

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: