

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011162/UVP3Q2**Date:** 07/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00086912200
Claimant Vehicle No :	SNC478Z	Insured Vehicle No :	SJF4547M
Date of Loss:	07/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208022/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC478Z	Engine No:	L15B3535476
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GK81004672
Reg. Date:	20/05/2016 (Man. Year: 2016)	Odometer:	116335 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,028.96	3,636.64	5,392.32	59.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	2,040.00	1,650.00	44.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,718.96	5,676.64	7,042.32	55.37
Approved Total (Overridden) (\$\$)		4,500.00		
Nett Amount (\$\$)	12,718.96	4,500.00	8,218.96	64.62

INSPECTION

Date of Assignment:	08/11/2022	Zoom Auto Werks - Kaki Bukit (HQ) BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE Singapore 417808
Date Inspected:	09/11/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Dec 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC478Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER SEAL	Necessary	68.00 FL	*68.00 FL
2	1		*REAR TAILGATE	Badly Dented	1,193.00 FL	*1,193.00 FL
3	2		*REAR TAILGATE DAMPERS	Not Necessary	396.20 FL	*- FL
4	1		*REAR TAILGATE INNER TRIM	Torn	552.70 FL	*312.20 FL
5	2		*REAR TAILGATE LAMPS	Not Necessary	681.60 FL	*- FL
6	1		*REAR TAILGATE INNER LOCK	Dented / Damaged	397.90 FL	*195.40 FL
7	1		*REAR TAILGATE LOCK CATCH	Not Necessary	48.70 FL	*- FL
8	1		*REAR TAILGATE LOGO	Necessary	99.80 FL	*45.00 FL
9	1		*REAR TAILGATE WEATHERSTRIP	Twisted	168.50 FL	*168.50 FL
10	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	125.60 FL	*82.00 FL
11	2		*REAR TAILLAMPS	Not Necessary	1,041.00 FL	*- FL
12	1		*REAR END PANEL	Dented / Bent	655.20 FL	*550.00 FL
13	1		*REAR END PANEL INNER GARNISH	Twisted	166.80 FL	*166.80 FL
14	1		*SET REAR KEYLESS SENSOR	Not Necessary	195.00 FL	*- FL
15	1		*REAR SENSOR BUZZER	Not Necessary	155.00 FL	*- FL
16	1		*REAR BUMPER	Dented	1,180.60 FL	*953.00 FL
17	1		*REAR BUMPER BEAM	No such part	78.50 FL	*- FL
18	2		*REAR BUMPER SIDE SPONGES	Not Necessary	172.80 FL	*- FL
19	2		*REAR BUMPER REFLECTOR	Not Necessary	172.80 FL	*- FL
20	2		*REAR BUMPER REFLECTOR GARNISHES	Not Necessary	181.60 FL	*- FL
21	2		*REAR BUMPER SIDE RETAINER	Necessary	69.40 FL	*69.40 FL
22	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	48.00 FL	*- FL
23	1		*REAR FLOOR BOARD TRAY	Repair	525.00 FL	*380.00 FL
24	1		*REAR SPARE TYRE PANEL	Repair	1,650.00 FL	*- FL
25	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
26	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
27	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
28	1		*REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
29	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,033.70	4,473.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,004.74	836.66
Total Parts (\$\$)	9,028.96	3,636.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING	New	150.00	60.00
7	PANEL BEATING	New	1,500.00	800.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	850.00
Gross Labour Cost (\$\$)			3,690.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >