

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS22011163/GNY3M4**Date:** 12/01/2023**REFERENCE**

Insured/Claimant: MUHAMMAD NABEEL RAHMAN S/O YAKUB
Date of Loss: 04/11/2022

Policy No: SP2000465454-01
Nature of Claim: OD

Claim No: 202222007937

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC3097E**
Make & Model: HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A) Engine No: G4FGBU237847
Reg. Date: 11/08/2011 (Man. Year: 2011) Chassis No: KMHDH41CMCU173755
Colour: White Odometer: 0 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$42,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/15 R17 Rear Tyre Size: 225/15 R17
Front Left Side: Continental 5 mm Rear Left Side: Continental 4 mm
Front Right Side: Continental 5 mm Rear Right Side: Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,394.00	1,779.60	1,614.40	47.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	850.00	280.00	24.78
Paintwork Labour	600.00	500.00	100.00	16.67
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,124.00	3,129.60	1,994.40	38.92
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	4,524.00	2,529.60	1,994.40	44.08
+ GST 7.00/7.00% (S\$)	316.68	177.07	139.61	44.09
Nett Amount (S\$)	4,840.68	2,706.67	2,134.01	44.08

INSPECTION

Date of Assignment: 08/11/2022 Present Location: Success United Pte Ltd (HQ)
Date Inspected: 09/11/2022 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC3097E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BONNET HINGE L/R (WCP)	Bent	110.00 F	*110.00 F
2	1		*FRONT BONNET (WCP)	Bent	480.00 F	*480.00 F
3	1		*FRONT BONNET WEATHERSTRIP (WCP)	Not Necessary	25.00 F	*- F
4	2		*FRONT HEADLAMP (L/RH) (WCP)	Not Necessary	700.00 F	*- F
5	2		*FRONT HEADLAMP BRACKET (L/RH) (WCP)	Not Necessary	56.00 F	*- F
6	1		*FRONT BONNET MECHANISM LOCK (WCP)	Bent	36.00 F	*36.00 F
7	1		*FRONT BUMPER ASSY (WCP)	Deformed	250.00 F	*250.00 F
8	2		*FRONT BUMPER SIDE HOLDER (L/RH) (WCP)	Not Necessary	50.00 F	*- F
9	1		*FRONT NO PLATE GARNISH (WCP)	Not Necessary	35.00 F	*- F
10	1		*FRONT BUMPER INNER SPONGE (WCP)	Cracked	85.00 F	*85.00 F
11	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	150.00 F	*- F
12	1		*FRONT GRILLE ASSY (WCP)	Cracked	125.00 F	*125.00 F
13	1		*HORN (WCP)	Not Necessary	48.00 F	*- F
14	1		*RADIATOR SUPPORT TOP COVER GARNISH (WCP)	Not Necessary	70.00 F	*- F
15	1		*RADIATOR SUPPORT PANEL (WCP)	Bent	380.00 F	*380.00 F
16	1		*AIR INTAKE DUCT (WCP)	Not Necessary	80.00 F	*- F
17	1		*AIRCON CONDENSER (WCP)	Not Necessary	240.00 F	*- F
18	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
19	1		*RADIATOR SUPPORT TOP COVER GARNISH CLIPS	Necessary	30.00 FS	*15.00 FS
20	1		*FRONT NO.PLATE WITH FRAME	Bent	45.00 FS	*45.00 FS
Supplementary #1						
21	2		*Radiator Side Air Guide L/R (WCP)	Missing	70.00 F	*70.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)		3,095.00	1,626.00
+ Margin on L,N Items 10.00/10.00% (S\$)		299.00	153.60
Total Parts (S\$)		3,394.00	1,779.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To putty and respray painting on front bonnet and bumper	New	600.00	500.00
<u>Labour Items</u>				
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	New	900.00	700.00
3	To remove, rearrange electrical wirings, check lighting	New	80.00	30.00
4	To remove, replace aircon parts, vacuum & refill gas	New	150.00	120.00
Gross Labour Cost (\$\$)			1,730.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >