

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SU220135
Policy No:	SP2000465454-01	Date of Loss:	04/11/2022
Vehicle Reg. No.:	SKC3097E	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Muhammad Nabeel Rahman S/O Yakub	Contact No:	+6583285694
Driver:	Muhammad Nabeel Rahman S/O Yakub		

Make/Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Vehicle Reg. Date:	11/08/2011
Vehicle Colour:	White		
Engine No:	G4FGBU237847	Chassis No:	KMHDH41CMCU173755
Odometer:	187837 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 5

Description of Accident/Loss REFER TO SKETCH PLAN.

Present Location: SUCCESS UNITED PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	3,317.00
Miscellaneous Items	0.00
Labour	1,130.00
Paintwork Labour	600.00
Towing	0.00
Calculated Gross Total (S\$)	5,047.00
- Excess (S\$)	600.00
(S\$)	4,447.00
+ GST 7.00% (S\$)	311.29
Nett Amount (S\$)	4,758.29

This claim is handled by: LAW YI TING

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2022)

Parts: 143 HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Success United Pte Ltd/SKC3097E/08/11/2022 14:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*FRONT BONNET HINGE L/R ✓ BT	0.00	0.00	*110.00 F
2	1		*FRONT BONNET ✓ BT	0.00	0.00	*480.00 F
3	1		*FRONT BONNET WEATHERSTRIP ✓ TWI	0.00	0.00	*25.00 F
4	2		*FRONT HEADLAMP (L/RH) ?	0.00	0.00	*700.00 F
5	2		*FRONT HEADLAMP BRACKET (L/RH) ?	0.00	0.00	*56.00 F
6	1		*FRONT BONNET MECHANISM LOCK ✓ BT	0.00	0.00	*36.00 F
7	1		*FRONT BUMPER ASSY ✓ DE	0.00	0.00	*250.00 F
8	2		*FRONT BUMPER SIDE HOLDER (L/RH) ?	0.00	0.00	*50.00 F
9	1		*FRONT NO PLATE GARNISH X NN	0.00	0.00	*35.00 F
10	1		*FRONT BUMPER INNER SPONGE ✓ CRA	0.00	0.00	*85.00 F
11	1		*FRONT BUMPER REINFORCEMENT ?	0.00	0.00	*150.00 F
12	1		*FRONT GRILLE ASSY ✓ CRA	0.00	0.00	*125.00 F
13	1		*HORN ?	0.00	0.00	*48.00 F
14	1		*RADIATOR SUPPORT TOP COVER GARNISH ?	0.00	0.00	*70.00 F
15	1		*RADIATOR SUPPORT PANEL ?	0.00	0.00	*380.00 F
16	1		*AIR INTAKE DUCT ?	0.00	0.00	*80.00 F
17	1		*AIRCON CONDENSER ?	0.00	0.00	*240.00 F
18	1		*FRONT BUMPER CLIPS ✓ NEC	0	0.00	*30.00 FS
19	1		*RADIATOR SUPPORT TOP COVER GARNISH CLIPS ✓ NEC	0	0.00	*30.00 FS
20	1		*FRONT NO.PLATE WITH FRAME ✓ BT	0	0.00	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,025.00
+ Margin on L,N Items 10.00% (S\$)	292.00

Total Parts (S\$)	3,317.00
--------------------------	-----------------

Success United Pte Ltd/SKC3097E/08/11/2022 14:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To putty and respray painting on front bonnet and bumper	New	600.00 500
Labour Items			
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	New	900.00 500
3	To remove, rearrange electrical wirings, check lighting	New	80.00 30
4	To remove, replace aircon parts, vacuum & refill gas	New	150.00 ?
Gross Labour Cost (\$\$)			1,730.00

Success United Pte Ltd/SKC3097E/08/11/2022 14:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



4 Days

P/P

Before paint photos

Guo Qiang - LKK

82880282

09/11/2022

Excess: \$600

Not Authorised