

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011165/UWP3M4**Date:** 13/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00024002201

Claimant Vehicle No : SJY3943J **Insured Vehicle No :** GY2881X

Date of Loss: 04/11/2022 Nature of Claim: TP Claim No: SNM22D208005/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY3943J**

Make & Model: MITSUBISHI LANCER, 1.6 GLX ABS AIRBAG 2WD 4DR (A) Engine No: 4G18KJ5212

Reg. Date: 27/08/2010 (Man. Year: 2010) Chassis No: JMYSRCS3AAU003538

Colour: White Odometer: 123376 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 5,518.00 | 1,624.40 | 3,893.60 | 70.56 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,850.00 | 800.00 | 1,050.00 | 56.76 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,368.00 | 2,424.40 | 4,943.60 | 67.10 |
| Approved Total (Overridden) (S\$) | | 1,900.00 | | |
| (S\$) | 7,368.00 | 1,900.00 | 5,468.00 | 74.21 |
| + GST 8.00/8.00% (S\$) | 589.44 | 152.00 | 437.44 | 74.21 |
| Nett Amount (S\$) | 7,957.44 | 2,052.00 | 5,905.44 | 74.21 |

INSPECTION

Date of Assignment: 08/11/2022

Date Inspected: 23/02/2023 Inspected At: FALCON-AIR AUTO SERVICES PTE LTD
BLK 9006 TAMPINES ST 93 #01-200
SINGAPORE 528840

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 13 Mar 2023) |
| Parts: | 143 | mitsubishi LANCER 1.6 GLX ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJY3943J) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------------|---------------------------|-------------|------------|
| 1 | 1 | | *BONNET | Repair | 1,393.00 FL | *- FL |
| 2 | 1 | | *HEADLAMP 2PCS | N/s Cracked (1Piece Only) | 1,638.00 FL | *819.00 FL |
| 3 | 2 | | *HEADLAMP LOWER BRACKET | Not Necessary | 272.00 FL | *- FL |
| 4 | 1 | | *RADIATOR GRILLE OUTER | Cut | 218.00 FL | *218.00 FL |
| 5 | 2 | | *RADIATOR GRILLE | Not Necessary | 256.00 FL | *- FL |
| 6 | 1 | | *RADIATOR GRILLE LOGO | Necessary | 45.00 FL | *45.00 FL |
| 7 | 1 | | *FRONT BUMPER | Cut | 916.00 FL | *781.00 FL |
| 8 | 1 | | *FRONT BUMPER CENTRE BRACKET | Not Necessary | 356.00 FL | *- FL |
| 9 | 1 | | *FRONT BUMPER LOWER GRILLE | Not Necessary | 148.00 FL | *- FL |
| 10 | 2 | | *FRONT BUMPER GARNISH | Not Necessary | 98.00 FL | *- FL |
| 11 | 1 | | *FRONT BUMPER LOWER SPOILER | Repair | 950.00 FL | *- FL |
| 12 | 1 | | *FRONT BUMPER REINFORCEMENT | Repair | 185.00 FL | *- FL |
| 13 | 1 | | *FRONT NUMBER PLATE GARNISH | Deformed | 185.00 FL | *105.00 FL |
| 14 | 1 | | *RADIATOR GRILLE CLIP | Not Necessary | 50.00 FS | *- FS |
| 15 | 1 | | *SET FRONT BUMPER CLIP | Necessary | 50.00 FS | *50.00 FS |
| 16 | 1 | | *FRONT BUMPER LOWER SPOILER CLIP | Not Necessary | 50.00 FS | *- FS |
| 17 | 1 | | *NUMBER PLATE | Not Necessary | 40.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|----------|----------|
| Sub Total (\$\$) | 6,850.00 | 2,018.00 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 1,332.00 | 393.60 |
| Total Parts (\$\$) | 5,518.00 | 1,624.40 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO FOCUS HEADLAMPS } | New | 50.00 | 20.00 |
| 2 | TO CHECK NESSARY WIRING } | New | 50.00 | 0.00 |
| 3 | TO RUST PROOF PANELS | New | 150.00 | 0.00 |
| 4 | TO REPAIR INNER PANEL,ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME | New | 800.00 | 300.00 |
| 5 | TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA | New | 800.00 | 480.00 |
| Gross Labour Cost (\$\$) | | | 1,850.00 | 800.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >