

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22011166/AGVY3E2**Date:** 16/02/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1002137254

Claimant Vehicle No : SLS5939S**Insured Vehicle No :** FBT9673U

Date of Loss: 05/11/2022

Nature of Claim: TP

Claim No: 289877

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLS5939S**

Make & Model: MAZDA 3, 1.5 SEDAN AT LED EU6 (A)

Engine No: P520465962

Reg. Date: 28/09/2017 (Man. Year: 2017)

Chassis No: JM6BN22A8J0176127

Colour: Bronze

Odometer: 41248 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Toyo 6 mm

Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,718.80	4,107.52	5,611.28	57.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,270.00	1,130.00	47.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,118.80	5,377.52	6,741.28	55.63
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	12,118.80	4,300.00	7,818.80	64.52

INSPECTION

Date of Assignment: 08/11/2022

Date Inspected: 08/11/2022 Inspected At:

Leang Automotive (Kaki Bukit)
AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Feb 2023)
Parts:	143	MAZDA 3 1.5 SEDAN AT LED EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS5939S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,083.30 F	*- FL
2	1		*FRONT BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
3	1		*FRONT BUMPER SIDE HOLDER LH	Not Necessary	38.30 F	*- FL
4	1		*HEADLAMP LH	Cut	3,565.00 F	*3,565.00 FL
5	1		*FRONT LH FENDER	Dented	417.50 F	*417.50 FL
6	1		*FRONT LH FENDER INNER SHIELD	Deformed	185.10 F	*185.10 FL
7	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
8	1		*FRONT LH WHEEL RIM	Not Necessary	1,000.00 FS	*- FS
9	1		*FRONT LH WING MIRROR	Damaged	456.60 F	*456.60 FL
10	1		*FRONT LH WING MIRROR SIGNAL LAMP	Cracked	85.80 F	*85.80 FL
11	1		*FRONT LH DOOR	Repair	1,120.90 F	*- FL
12	1		*FRONT LH DOOR GLASS	Cut	386.90 F	*386.90 FL
13	1		*FRONT LH DOOR FRAME BLACK TAPE	Not Necessary	50.00 FS	*- FS
14	1		*REAR LH DOOR	Repair	1,219.40 F	*- FL
15	1		*REAR LH DOOR FRAME BLACK TAPE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,718.80	5,126.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,019.38
Total Parts (\$\$)	9,718.80	4,107.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	500.00
2	SPRAY PAINTING	New	1,000.00	700.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER FRONT AND REAR DOOR FITTINGS	New	300.00	0.00
5	TO APPLY TUFF COAT	New	150.00	40.00
Gross Labour Cost (\$\$)			2,400.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >