

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT                   |  |                         |                |                       |                         |
|--|--|-------------------------|----------------|-----------------------|-------------------------|
|  | INCOME INSURAN   |                         | Ref:           | CS/INC22011176/Aqy3m4 |                         |
|  | 75 BRAS BASAH R<br>INCOME CENTRES  | OAD<br>SINGAPORE 189557 |                | Date:                 | 27/01/2023              |
|  | ATTN: DAVID PHU  | A                       |                | Code:                 | INC                     |
| 1. Policy Particulars :- THIRD PARTY CLAIM |  |                         |                |                       |                         |
|  | Insured Veh.   | PC 5439E                | Veh. Inspected | ł                     | GBF 7005K               |
|  | Policy No.   |                         | Coverage (\$)  |                       | 0.00                    |
|  | Claim No.  | MT/1196003-001          | Excess (\$)    |                       | 0.00                    |
|  | Assign From  | HAZALYSA BINTE IBRAHIM  | Assign Date    |                       | 08/11/2022              |
| 2. Vehicle Particulars & Condition         |  |                         |                |                       |                         |
|  | Make & Model   | NISSAN NV200            | c.c            |                       | 1597                    |
|  | Engine No.   | HIDDEN                  | Year of Reg.   |                       | 2017                    |
|  | Chassis No.  | VM20102518              | Colour         |                       | BLACK                   |
|  | Odometer   | 111689 KM               | Steering       |                       | IN ORDER                |
|  | Brakes   | IN ORDER                | Modification   |                       | NIL                     |
|  | General  | GOOD                    |                |                       |                         |
| 3. Conditions of Tyres                     |  |                         |                |                       |                         |
|  |  | Size                    | Make           |                       | Balance                 |
|  | R/H Front Tyre   | 185/70 R14              | WEST LAKE      |                       | 6 mm                    |
|  | L/H Front Tyre   | 185/70 R14              | WEST LAKE      |                       | 6 mm                    |
|  | R/H Rear Tyre  | 185/70 R14              | WEST LAKE      |                       | 6 mm                    |
|  | L/H Rear Tyre  | 185/70 R14              | WEST LAKE      |                       | 6 mm                    |
| 4. Description of Damages                  |  |                         |                |                       |                         |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.   |                         |                |                       |                         |
|  | DAMAGES SEE DETAILS.   |                         |                |                       |                         |
| 5.   | General Information  |                         |                |                       |                         |
|  | Accident Date  | 03/11/2022              | Inspect Date / | Time                  | 08/11/2022 ( 04:20 PM ) |
|  | Survey held at HD PERFECT AUTOWORK PTE LTD  8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875                      |                         |                |                       |                         |
|  |  |                         |                |                       |                         |
| 5a.  | Remarks  |                         |                |                       |                         |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                         |                |                       |                         |
| 5b.  | Estimate Days of Repair  |                         |                |                       |                         |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days   |                         |                |                       |                         |
|  |  |                         |                |                       |                         |