



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: DAVID PHUA

Ref: CS/INC22011177/Awy3e2

Date: 03/02/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 7942B	Veh. Inspected	PC 3934E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1195750-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	08/11/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE COMMUTER	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KDH2230022853	Colour	WHITE
Odometer	199906 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	FALKEN	6 mm
L/H Front Tyre	225/50 R18	FALKEN	6 mm
R/H Rear Tyre	225/50 R18	FALKEN	6 mm
L/H Rear Tyre	225/50 R18	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/11/2022	Inspect Date / Time	08/11/2022 (04:33 PM)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
--	------------------------