

ASIS REC BY: Taufik

REF: CS/INC2201180/Tg3

ASSIGNMENT

2028 June
2009, Na

From: _____ Date: _____
Estimated cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$63K
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS - WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMP3457H Yr Regn: 2009, Na
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Mercedes Benz E250 C.C. 1796
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD2120472A09-B089
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modl: NII / S/Rim / STD A/Rim or _____
Tyre Size: F: 225/45R17
R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIR / SUMI /
TOYO / YOKO or _____

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 08/11/2009 440pm

Survey held at SAT

Des. of Damages: Front Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh finalised LS \$3800, 3 days. (Red \$4526.50, 54%)

Date/Time, File Pass to? ☐ : Preli. Report
1) 02/05 Typist ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:	
Transportation:	
S + RS \$:	
Photos	
Others	

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. invs (\$)
☐ : Weed and

Report Form: TP
Lum. Sum 3800

SAT (SG) PTE LTD

61 Ubi Road 1 #04-14 Oxley Bizhub Singapore 408727

TEL: 6242 2212 FAX: 62426169

Vehicle No: SMP3457H

Accident Date : 05/11/2022

Model No. Mercedes Benz E250

Owner : Samuel Colin Joseph

Chassis no. WDD2120472A095089

Date of Estimate : 10/11/2022

Repair Estimate

List Items:	Qty	Unit Price	Total Amount
1 Front Bumper	1	\$1,500.00	1298 \$1,500.00 del ✓
2 Front Distance Sensor (Centre)	2	\$280.00	\$560.00 Xnn
3 Front Distance Sensor (Outer)	1	\$260.00	\$1,040.00 nw / 260
4 Front Distance Sensor Wire (Set)	1	\$120.00	\$120.00 Xnn
5 Front Bumper Headlamp Washer Cap	1	\$105.00	\$105.00 mis ✓
6 Front LH Headlamp	1	\$2,880.00	1268 \$2,880.00 crn ✓
7 Front left HID Headlamp light bulb	1	\$180.00	\$180.00 Xnn
8 Headlamp Control Module Ballast	1	\$540.00	340 \$540.00 del ✓
9 Washer Fluid Tank.	1	\$250.00	\$250.00 Xnn

Sub-Total Amount = \$5,115.00

10% Discount = \$511.50

Sub-Total = \$5,626.50

3371

3033.90

Labour charges

1 Panel beating for replace and repair affected parts	\$1,000.00	500
2 Spray painting	\$750.00	500
3 Apply putty and anti-corrosion to affected parts.	\$150.00	30
4 Wiring / bulb checking	\$50.00	30
5 Replace of washer tank	\$200.00	X
6 Remove & refix ^{front} bumper reverse sensor	\$100.00	30
7 Programming for Headlamp control module ballast.	\$450.00	100
	<u>\$2,700.00</u>	1190

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan J M 97495749

Total parts	=	\$5,626.50
Total labour	=	\$2,700.00
Total Amount	=	\$8,326.50

8/11/22 2:44pm

L/S Resurvey after repair

Tan J M @ lkkauto.com

03 days

3033.90

1190

4223.90

L/S \$3400, 03 days