

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011183/EVP3Q2**Date:** 19/01/2023**REFERENCE**

Insured/Claimant: LIM SWEE PANG Policy No: MPC202200454CN
Date of Loss: 01/11/2022 Nature of Claim: OD Claim No: SNM22D207868/C01/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNH4369C**
Make & Model: TOYOTA RAIZE, 1.0 X CVT (A) Engine No: WA0038625
Reg. Date: 27/10/2022 (Man. Year: 2022) Chassis No: A201A0003468
Colour: White Odometer: 615 km
Engine Capacity: 1196 cc
Market Value/New Car Price: S\$145,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R16 Rear Tyre Size: 195/65 R16
Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,153.00	8,012.00	1,141.00	12.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,288.43	1,074.95	213.48	16.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,441.43	9,086.95	1,354.48	12.97
+ GST 7.00/7.00% (S\$)	730.90	636.09	94.81	12.97
Nett Amount (S\$)	11,172.33	9,723.04	1,449.29	12.97

INSPECTION

Date of Assignment: 08/11/2022 Present Location: Goldbell Engineering Pte Ltd (Tuas)
Date Inspected: 08/11/2022 Inspected At: PANDAN LOOP INDUSTRIAL ESTATE, #01-12
Estimated Period of Repair: 7.0 days Repairer: Goldbell Engineering Pte Ltd (Tuas)

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts: 144	TOYOTA RAIZE 1.0 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SNH4369C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts		4,906.00 F	*3,765.00 F
Supplementary #1						
2	1	53121-B1120	*RAD GRILLE MLDG	Broken	135.00 F	*135.00 F
3	1	52116-B1061	*FRT BUMPER S/RETAINER LH	Broken	55.00 F	*55.00 F
4	1	53209-B1020	*BRACE SUB-ASSY, HOOD LOCK SUPPORT	Bent	265.00 F	*265.00 F
5	1	53208-B1030	*SUPPORT SUB-ASSY, HOOD LOCK	Bent	240.00 F	*240.00 F
6	1	53216-B1100	*SUPPORT, RADIATOR, UPPER	Bent	145.00 F	*145.00 F
7	1	16400-B1-481	*RADIATOR	Bent	650.00 F	*650.00 F
8	1	53811-B1320	*FRT FENDER RH	Bent	325.00 F	*325.00 F
9	1	53202-B1050	*SUPPORT SUB-ASSY, RADIATOR, RH	Bent	145.00 F	*145.00 F
10	1	53203-B1050	*SUPPORT SUB-ASSY, RADIATOR, LH	Bent	145.00 F	*145.00 F
11	1	53812-B1320	*FRT FENDER LH	Bent	325.00 F	*325.00 F
12	1	52115-B1061	*FRT BUMPER S/RETAINER RH	Broken	55.00 F	*55.00 F
13	1	53401-B1070	*FRT BONNET HINGE RH	Bent	48.00 F	*48.00 F
14	1	53402-B1070	*FRT BONNET HINGE LH	Bent	48.00 F	*48.00 F
15	1	53510-B1130	*FRT BONNET LOCK	Bent	85.00 F	*85.00 F
16	1	53445-B1030	*WIPER GARNISH S/SEAL, RH	Broken	40.00 F	*40.00 F
17	1	53446-B1030	*WIPER GARNISH S/SEAL, LH	Broken	40.00 F	*40.00 F
18	1	53218-B1080	*SUPPORT, RADIATOR, LOWER	Bent	240.00 F	*240.00 F
19	1	88460-B1030	*A/C CONDENSER	Bent	700.00 F	*700.00 F
20	1	17700-B1140	*AIR CLEANER	Broken	360.00 F	*360.00 F
21	1	53341-B1090	*FRT BONNET INSULATOR	Crushed	130.00 F	*130.00 F
22	1	90467-T001409050	*FRT BONNET INSULATOR CLIP (6 PCS EACH \$2.00)	Necessary	12.00 F	*12.00 F
23	1	53125-B1050	*BUMPER GRILLE BRKT	Bent	33.00 F	*33.00 F
24	1	T08889-80110	*COOLANT (4L X 4) RED CAP	Necessary	26.00 F	*26.00 F

F=Franchise part.

Total Parts (\$\$) 9,153.00 8,012.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Labour	New	1,288.43	1,074.95
Gross Labour Cost (\$)			1,288.43	1,074.95

Report was unsubmitted during this print-out.

< END OF ESTIMATES >