

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011184/KVP3Q2**Date:** 13/04/2023**REFERENCE**

Insured/Claimant:	RED ROOSTER TRANSPORT SERVICES	Policy No:	DMB1SNW00015922200
Date of Loss:	05/11/2022	Nature of Claim:	OD
		Claim No:	SNM22D208007/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC9919K	Engine No:	1KD2434678
Make & Model:	TOYOTA HIACE, 3.0 D Commuter (M)	Chassis No:	KDH2230021026
Reg. Date:	10/10/2014 (Man. Year: 2014)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$28,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,440.00	23,810.00	7,630.00	24.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,997.37	3,805.57	191.80	4.80
Paintwork Labour	0.00	0.00	0.00	
Towing	260.00	0.00	260.00	100.00
Calculated Gross Total (S\$)	35,697.37	27,615.57	8,081.80	22.64
Approved Total (Overridden) (S\$)		22,000.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	35,697.37	20,000.00	15,697.37	43.97
+ GST 7.00/8.00% (S\$)	2,498.82	1,600.00	898.82	35.97
Nett Amount (S\$)	38,196.19	21,600.00	16,596.19	43.45

INSPECTION

Date of Assignment:	08/11/2022 Present Location:	Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	08/11/2022 Inspected At:	5035 ANG MO KIO INDUSTRIAL PARK 2, #01-367, ANG MO KIO
Estimated Period of Repair:	18.0 days	Repairer: Goldbell Engineering Pte Ltd (Tuas)

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Apr 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 D Commuter (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC9919K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts		31,440.00 F	*23,810.00 F
F=Franchise part.						
Total Parts (S\$)					31,440.00	23,810.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total of Labour	New	2,788.80	2,704.80
2	Total Paint Including Material	New	1,208.57	1,100.77
Gross Labour Cost (S\$)			3,997.37	3,805.57

Report was unsubmitted during this print-out.

< END OF ESTIMATES >